

OIL ANALYSIS REPORT

IRON SHORING 100-037

Component **Right Final Drive**

NOT GIVEN (--- GAL)

Sample Rating Trend



Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the

Fluid Condition

The condition of the oil is acceptable for the time in service.

			Jun2023	Dec2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0872918	LH0265811	
Sample Date		Client Info		06 Dec 2023	06 Jun 2023	
Machine Age	hrs	Client Info		0	1543	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		N/A	Changed	
Sample Status				NORMAL	NORMAL	
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>500	319	290	
Chromium	ppm	ASTM D5185(m)	>10	6	6	
Nickel	ppm	ASTM D5185(m)	>10	1	<1	
Titanium	ppm	ASTM D5185(m)		4	5	
Silver	ppm	ASTM D5185(m)		<1	0	
Aluminum	ppm	ASTM D5185(m)	>25	66	73	
Lead	ppm	ASTM D5185(m)	>25	2	1	
Copper	ppm	ASTM D5185(m)	>50	70	55	
Tin	ppm	ASTM D5185(m)	>10	<1	<1	
Antimony	ppm	ASTM D5185(m)	>5	0	0	
Vanadium	ppm	ASTM D5185(m)		0	<1	
Beryllium	ppm	ASTM D5185(m)		0	0	
Cadmium	ppm	ASTM D5185(m)		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		5	7	
Barium	ppm	ASTM D5185(m)		3	4	
Molybdenum	ppm	ASTM D5185(m)		0	0	
Manganese	ppm	ASTM D5185(m)		7	7	
Magnesium	ppm	ASTM D5185(m)		21	23	
Calcium	ppm	ASTM D5185(m)		198	220	
Phosphorus	ppm	ASTM D5185(m)		171	196	
Zinc	ppm	ASTM D5185(m)		71	67	
Sulfur	ppm	ASTM D5185(m)		8061	7826	
Lithium	ppm	ASTM D5185(m)		<1	<1	
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>75	204	214	
Sodium	ppm	ASTM D5185(m)		32	37	
Potassium	ppm	ASTM D5185(m)	>20	25	26	



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: WC0872918

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 RONI/IRON SHORE EXCAVATING LTD. Recieved : 02603312

: 14 Dec 2023 : 18 Dec 2023 Diagnosed Diagnostician

: Kevin Marson

100 MACINTOSH BLVD VAUGHAN, ON CA L4K 4P3 Contact: Service Team

service.team@roni.ca

Test Package : MOBCE (Additional Tests: Visual) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

: 5696397

T: F: