


OIL ANALYSIS REPORT

PUMPHOUSE/BACKWASH PUMPS C - Backwash Pump 2 - OB

Gear Lube System

PETRO CANADA HYDREX AW 100 (1 GAL)





DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you follow the water drain-off procedure for this component. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

Excessive free water present.


Fluid Condition

The oil viscosity is lower than typical, possibly indicating the addition of lighter grade oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0898672	WC0850114	WC0824392
Sample Date		Client Info		10 Jan 2024	16 Aug 2023	31 May 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINATION	V	method	limit/base	current	history1	history2
Water		WC Method	>1	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*	>DFLT	14	0	34
Iron	ppm	ASTM D5185(m)	>150	22	3	115
Chromium	ppm	ASTM D5185(m)	>10	<1	0	<1
Nickel	ppm	ASTM D5185(m)	>10	<1	<1	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	1	0
Aluminum	ppm	ASTM D5185(m)	>25	<1	<1	<1
Lead	ppm	ASTM D5185(m)	>100	3	1	<1
Copper	ppm	ASTM D5185(m)	>50	24	13	3
Tin	ppm	ASTM D5185(m)	>10	0	0	0
Antimony	ppm	ASTM D5185(m)	>5	0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	<1	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	0	<1	<1
Barium	ppm	ASTM D5185(m)	0	5	7	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)	0	0	0	<1
Magnesium	ppm	ASTM D5185(m)	0	1	<1	<1
Calcium	ppm	ASTM D5185(m)	50	37	43	48
Phosphorus	ppm	ASTM D5185(m)	330	302	324	356
Zinc	ppm	ASTM D5185(m)	430	355	379	396
Sulfur	ppm	ASTM D5185(m)	760	2739	2595	2851
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	1	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	3	2	3
Sodium	ppm	ASTM D5185(m)		<1	<1	<1
Potassium	ppm	ASTM D5185(m)	>20	1	<1	<1
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.60	0.35	0.57	0.51



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number **Unique Number** Test Package

: WC0898672

: 02608059 : 5709145 : IND 2

Recieved Diagnosed

: 15 Jan 2024 Diagnostician : Kevin Marson

: 10 Jan 2024

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 STELCO - BOSC - Basic Oxygen Slab Caster 2330 Regional Road #3, Door: BOSC8

NANTICOKE, ON CA NOA 1L0

Contact: Tom Walden Thomas.Walden@stelco.com

T: (519)587-4541 F: (519)587-7702

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.