


OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



MANITOU 735 FOR422

Component

Transmission (Manual)

ATF (--- GAL)

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the fluid.


Fluid Condition

The condition of the fluid is acceptable for the time in service.

			Oct2023	Dec2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0886085	WC0865519	
Sample Date		Client Info		31 Dec 2023	29 Oct 2023	
Machine Age	hrs	Client Info		10269	10073	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		Not Changd	Not Changd	
Sample Status				NORMAL	ATTENTION	
CONTAMINATION	V	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>200	17	17	
Chromium	ppm	ASTM D5185(m)	>5	0	0	
Nickel	ppm	ASTM D5185(m)	>5	<1	<1	
Titanium	ppm	ASTM D5185(m)		0	0	
Silver	ppm	ASTM D5185(m)	>7	0	<1	
Aluminum	ppm	ASTM D5185(m)	>25	2	1	
Lead	ppm	ASTM D5185(m)	>45	<1	1	
Copper	ppm	ASTM D5185(m)	>225	13	13	
Tin	ppm	ASTM D5185(m)	>10	0	0	
Antimony	ppm	ASTM D5185(m)		0	0	
Vanadium	ppm	ASTM D5185(m)		0	0	
Beryllium	ppm	ASTM D5185(m)		0	0	
Cadmium	ppm	ASTM D5185(m)		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		96	98	
Barium	ppm	ASTM D5185(m)		0	<1	
Molybdenum	ppm	ASTM D5185(m)		<1	<1	
Manganese	ppm	ASTM D5185(m)		<1	<1	
Magnesium	ppm	ASTM D5185(m)		21	▲ 21	
Calcium	ppm	ASTM D5185(m)		2316	▲ 2354	
Phosphorus	ppm	ASTM D5185(m)		806	▲ 784	
Zinc	ppm	ASTM D5185(m)		871	A 891	
Sulfur	ppm	ASTM D5185(m)		2631	▲ 2497	
Lithium	ppm	ASTM D5185(m)		<1	<1	
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>125	5	5	
Sodium	ppm	ASTM D5185(m)		4	4	
Potassium	ppm	ASTM D5185(m)	>20	5	1	



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number**

Test Package : MOB 1

: 02608239

: WC0886085 : 5709325

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Recieved Diagnosed : Wes Davis Diagnostician

: 11 Jan 2024 : 11 Jan 2024

Agnico Eagle Canada 1350 Government Rd. W, MACASSA COMPLEX Kirkland Lake, ON

CA P2N 3J1 Contact: Jay Gould

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Macassa Mobile UGP lanning@agnicoeagle.comT: (705)567-5208

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: (705)567-5221

Contact/Location: Jay Gould - KIR370KIR