

## **PROBLEM SUMMARY**

## Sample Rating Trend

## ISO

# 31 WOODROOM

BLOWER CHIPS TO DIGESTER - OUTBOARD BRG (S/N 315803B)

Componen


**Outboard Blower** 

ESSO NUTO H ISO 68 (30 GAL)





## **COMPONENT CONDITION SUMMARY**



## **RECOMMENDATION**

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS									
Sample Status			SEVERE	SEVERE	SEVERE				
Particles >4µm	ASTM D7647	>2500	<b>22377</b>	<b>51809</b>	98286				
Particles >6µm	ASTM D7647	>640	<u>2251</u>	7357	23480				
Oil Cleanliness	ISO 4406 (c)	>18/16/13	<b>22/18/12</b>	23/20/15	<b>2</b> 4/22/15				

Customer Id: STANAC Sample No.: WC Lab Number: 02610433 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

#### **RECOMMENDED ACTIONS** Action **Status** Date Done By Description Change Filter ? We recommend you service the filters on this component. Resample ? Resample in 30-45 days to monitor this situation. The air breather requires service. If unrated, we recommend that you replace with a ? **Check Breathers** suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather Check Seals ? Check seals and/or filters for points of contaminant entry.

## HISTORICAL DIAGNOSIS

## 11 Jul 2023 Diag: Wes Davis

ISO



We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



## 05 Jan 2023 Diag: Wes Davis

ISO



Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. Particles  $>6\mu m$  are severely high. Particles  $>4\mu m$  are severely high. Oil Cleanliness are severely high. Particles  $>14\mu m$  are abnormally high. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



#### 21 Jun 2022 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





## **OIL ANALYSIS REPORT**

# 31 WOODROOM

## BLOWER CHIPS TO DIGESTER - OUTBOARD BRG (S/N 315803B)

**Outboard Blower** 

ESSO NUTO H ISO 68 (30 GAL)



## DIAGNOSIS

## Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

## Wear

All component wear rates are normal.

## Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.


## **Fluid Condition**

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC	WC	WC
Sample Date		Client Info		16 Jan 2024	11 Jul 2023	05 Jan 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
CONTAMINATION	٧	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0	0	0
Iron	ppm	ASTM D5185(m)	>20	4	5	8
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	0	0	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>20	<1	0	<1
Lead	ppm	ASTM D5185(m)	>20	0	0	<1
Copper	ppm	ASTM D5185(m)	>20	<1	<1	1
Tin	ppm	ASTM D5185(m)	>20	0	<1	0
Antimony	ppm	ASTM D5185(m)		0	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	0	<1	1
Barium	ppm	ASTM D5185(m)	0	0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	<1
Magnesium	ppm	ASTM D5185(m)	5	<1	1	5
Calcium	ppm	ASTM D5185(m)	50	50	51	56
Phosphorus	ppm	ASTM D5185(m)	330	325	360	373
Zinc	ppm	ASTM D5185(m)	420	391	428	419
Sulfur	ppm	ASTM D5185(m)	3100	7187	6871	6375
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	2	4	10
Sodium	ppm	ASTM D5185(m)		0	<1	0
Potassium	ppm	ASTM D5185(m)	>20	<1	<1	<1



## OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number **Unique Number** 

: WC

Recieved : 02610433 Diagnosed : 5711519

Test Package : IND 2 ( Additional Tests: PQ, PrtCount, TAN Man )

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : 22 Jan 2024 : 24 Jan 2024

Diagnostician : Wes Davis

AV GROUP NB INC. 103 PINDER ROAD,, NACKAWIC MILL NACKAWIC, NB

**CA E6G 1W4** Contact: Basil Fadulalla

basil.fadulalla@adityabirla.com

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

T: F:

Contact/Location: Basil Fadulalla - STANAC