


PROBLEM SUMMARY


Area [37713] WESTING HOUSE TERTIARY #1 (S/N IS-72P420)

Bearing

AW HYDRAULIC OIL ISO 68 (--- GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 68. Please confirm. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS									
Sample Status			SEVERE						
Particles >4µm	ASTM D7647	>10000	103940						
Particles >6µm	ASTM D7647	>2500	40911						
Particles >14µm	ASTM D7647	>160	<u> </u>						
Oil Cleanliness	ISO 4406 (c)	>20/18/14	4 24/23/17						
PrtFilter				no image	no image				

Customer Id: WAJKIR **Sample No.:** WC0919623 Lab Number: 02622033 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Alert			?	The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 68. Please confirm.			
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Seals			?	Check seals and/or filters for points of contaminant entry.			

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

[37713] WESTING HOUSE TERTIARY #1 (S/N IS-72P420)

Bearing

AW HYDRAULIC OIL ISO 68 (--- GAL)





DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 68. Please confirm. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

				Mar2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0919623		
Sample Date		Client Info		06 Mar 2024		
Machine Age	mths	Client Info		12		
Oil Age	mths	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				SEVERE		
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0		
Iron	ppm	ASTM D5185(m)	>20	0		
Chromium	ppm	ASTM D5185(m)	>20	0		
Nickel	ppm	ASTM D5185(m)	>20	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>20	<1		
Lead	ppm	ASTM D5185(m)	>20	<1		
Copper	ppm	ASTM D5185(m)	>20	4		
Tin	ppm	ASTM D5185(m)	>20	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	5	0		
Barium	ppm	ASTM D5185(m)	5	0		
Molybdenum	ppm	ASTM D5185(m)	5	0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)	25	<1		
Calcium	ppm	ASTM D5185(m)	200	53		
Phosphorus	ppm	ASTM D5185(m)	300	349		
Zinc	ppm	ASTM D5185(m)	370	431		


777

<1

0

<1

1



Sulfur

Lithium

Silicon

Sodium

Potassium

CONTAMINANTS

ppm

ppm

ppm

ppm

ppm

ASTM D5185(m)

ASTM D5185(m)

ASTM D5185(m)

ASTM D5185(m) >15


ASTM D5185(m) >20

2500

history



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: WC0919623 : 02622033

Unique Number : 5747152

: 14 Mar 2024 Received **Tested** : 19 Mar 2024 Diagnosed

: 19 Mar 2024 - Kevin Marson

Wajax - NorthPoint 475 Archer Drive Kirkland Lake, ON **CA P2N 3M6** Test Package: IND 2 (Additional Tests: BottomAnalysis, FILTERPATCH, PQ, PrtCount, PrtFiltetontact: Derek Garvin

To discuss this sample report, contact Customer Service at 1-800-268-2131.

dgarvin@northpointts.com T: (705)568-6355

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: