

OIL ANALYSIS REPORT



TOYOTA LANDCRUISER FMC042

Component

Diesel Engine

DIESEL ENGINE OIL SAE 15W40 (--- GAL)

DIAGNOSIS

Recommendation

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. No other corrective action is recommended at this time.

Wear

Metal levels are typical for a new component breaking in.

Contamination

Light fuel dilution occurring. No other contaminants were detected in the oil.

▲ Fluid Condition


Viscosity of sample indicates oil is within SAE 30 range, advise investigate. The condition of the oil is acceptable for the time in service.


Samp	Sample Rating Trend					
	Ma ² 0	24				
method	limit/base	current	history1	r		


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0892427		
Sample Date		Client Info		19 Mar 2024		
Machine Age	hrs	Client Info		264		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINATION	V	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
Glycol		WC Method	7 0.2	NEG		
			11 11 11		1111	111
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>100	40		
Chromium	ppm	ASTM D5185(m)	>20	<1		
Nickel	ppm	ASTM D5185(m)	>4	0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)	>3	0		
Aluminum	ppm	ASTM D5185(m)	>20	4		
Lead	ppm	ASTM D5185(m)	>40	1		
Copper	ppm	ASTM D5185(m)	>330	75		
Tin	ppm	ASTM D5185(m)	>15	5		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	250	37		
Barium	ppm	ASTM D5185(m)	10	2		
Molybdenum	ppm	ASTM D5185(m)	100	101		
Manganese	ppm	ASTM D5185(m)		1		
Magnesium	ppm	ASTM D5185(m)	450	41		
Calcium	ppm	ASTM D5185(m)	3000	4133		
Phosphorus	ppm	ASTM D5185(m)	1150	1048		
Zinc	ppm	ASTM D5185(m)	1350	1289		
Sulfur	ppm	ASTM D5185(m)	4250	3475		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	128		
Sodium	ppm	ASTM D5185(m)	>158	10		
Potassium	ppm	ASTM D5185(m)	>20	2		
Fuel	%	ASTM D7593*	>5	1.6		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	0.2		
Nitration	Abs/cm	ASTM D7624*	>20	6.8		
Sulfation	Abs/.1mm	ASTM D7415*	>30	16.7		



OIL ANALYSIS REPORT









CALA ISO 17025:2017 Accredited

Laboratory Sample No. Lab Number Unique Number : 5749744

: WC0892427 : 02624625

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received **Tested**

Test Package : MOB 1 (Additional Tests: FuelDilution, PercentFuel, Visual)

: 26 Mar 2024 Diagnosed

: 27 Mar 2024 : 27 Mar 2024 - Kevin Marson

Agnico Eagle Canada 1350 Government Rd. W, MACASSA COMPLEX Kirkland Lake, ON

CA P2N 3J1 Contact: Mitch Lamontagne

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

 $AEM_KL_macassa oil sample results@agnicoeagle.com$ T: (705)567-5208

F: (705)567-5221