


OIL ANALYSIS REPORT



Machine Id **CATERPILLAR 320B EXC01**

Hydraulic System Fluid TLO-4 (--- GAL)



DIAGNOSIS

Recommendation

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using MOB 2 test kits, this testkit includes Particle Count to determine the ISO cleanliness of the fluid.

Wear

Iron ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion.

Contamination

There is no indication of any contamination in the component(unconfirmed).


Fluid Condition

The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0920172		
Sample Date		Client Info		07 Apr 2024		
Machine Age	hrs	Client Info		19178		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				ABNORMAL		
CONTAMINATION	N	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0		
Iron	ppm	ASTM D5185(m)	>20	<u>▲</u> 37		
Chromium	ppm	ASTM D5185(m)	>10	3		
Nickel	ppm	ASTM D5185(m)	>10	0		
Titanium	ppm	ASTM D5185(m)		<1		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>10	6		
Lead	ppm	ASTM D5185(m)	>10	3		
Copper	ppm	ASTM D5185(m)	>75	72		
Tin	ppm	ASTM D5185(m)	>10	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		81		
Barium	ppm	ASTM D5185(m)		<1		
Molybdenum	ppm	ASTM D5185(m)		6		
Manganese	ppm	ASTM D5185(m)		<1		
Magnesium	ppm	ASTM D5185(m)		61		
Calcium	ppm	ASTM D5185(m)		1873		
Phosphorus	ppm	ASTM D5185(m)		884		
Zinc	ppm	ASTM D5185(m)		991		
Sulfur	ppm	ASTM D5185(m)		3789		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	6	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	16		
Sodium	ppm	ASTM D5185(m)		7		
Potassium	ppm	ASTM D5185(m)	>20	5		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory

Sample No.

: WC0920172 Lab Number : 02628490 Unique Number : 5761622

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

Received : 12 Apr 2024 **Tested** : 15 Apr 2024 Diagnosed : 15 Apr 2024 - Kevin Marson

Agnico Eagle Canada 1350 Government Rd. W, MACASSA COMPLEX Kirkland Lake, ON CA P2N 3J1

Test Package : MOB 1 (Additional Tests: PQ) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Contact: Jay Gould MacassaMobileUGPlanning@agnicoeagle.com T: (705)567-5208

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: (705)567-5221 Contact/Location: Jay Gould - KIR370KIR