

OIL ANALYSIS REPORT

Sample Rating Trend

Rio Can Ch#1 [GTT224-439 396599] CARRIER 0704Q69017 Chiller

REFRIGERATION OIL (POE) (--- GAL)

DIAGNOSIS

Recommendation

The operation of this unit should be reviewed closely by a service engineer. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.

Area

A Wear

Tin ppm levels are abnormal. Aluminum ppm levels are noted. The tin reading shows moderate wear occurring on the compressor bearings or motor bearings.

Contamination

The water content is negligible. There is no indication of any contamination in the oil.

Fluid Condition

The AN level is acceptable for this fluid.

SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GTT0003247	GTT1872	GTT1873
Sample Date		Client Info		06 Jun 2024	13 Apr 2022	14 Feb 2017
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ATTENTION	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>8	3	2	<1
Chromium	ppm	ASTM D5185(m)	>2	0	<1	<1
Nickel	ppm	ASTM D5185(m)		0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)	>2	0		
Aluminum	ppm	ASTM D5185(m)	>3	6	<1	<1
Lead	ppm	ASTM D5185(m)	>2	<1	<1	<1
Copper	ppm	ASTM D5185(m)	>8	7	4	<1
Tin	ppm	ASTM D5185(m)	>4	4 5	<1	<1
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1		
Barium	ppm	ASTM D5185(m)	0	0		
Molybdenum	ppm	ASTM D5185(m)	0	0		
Manganese	ppm	ASTM D5185(m)	0	<1		
Magnesium	ppm	ASTM D5185(m)	0	<1		
Calcium	ppm	ASTM D5185(m)	10	0		
Phosphorus	ppm	ASTM D5185(m)	250	4		
Zinc	ppm	ASTM D5185(m)	0	10	6	10
Sulfur	ppm	ASTM D5185(m)	400	43		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	16		
Sodium	ppm	ASTM D5185(m)		<1		
Potassium	ppm	ASTM D5185(m)	>20	<1		
ppm Water	ppm	ASTM D6304*	>200	9	379	35
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.07	0.09	0.080	0.087



OIL ANALYSIS REPORT

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)		58.6		
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image
GRAPHS			_			



Lab Number : 02640967 Tested : 12 Jun 2024 Vaughan, ON Unique Number : 5798506 Diagnosed : 14 Jun 2024 - Bill Quesnel Test Package : IND 2 (Additional Tests: KV40) Contact: Service Manager To discuss this sample report, contact Customer Service at 1-905-847-9300 Ext 26. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Damages: Seller shall in no event be liable for special, incidental, or consequential damages, of a commercial nature, resulting from any cause.

: 10 Jun 2024

Received

Report Id: GTT0000257 [WCAMIS] 02640967 (Generated: 06/14/2024 15:22:25) Rev: 1

Sample No. : GTT0003247

Contact/Location: Service Manager - GTT0000257 Page 2 of 2

Modern Niagara Building Services

8125 Hwy 50

CA L4H 4S6

T:

F: