


OIL ANALYSIS REPORT



Machine Id **NEW FLYER 1014**

Diesel Engine

SAFETY-KLEEN PERFORMANCE PLUS XHD-7 15W40 (--- GAL)





DIAGNOSIS

Recommendation

We advise that you check the fuel injection system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

▲ Contamination

There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition

Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0937238	WC0917554	WC0877985
Sample Date		Client Info		05 Jun 2024	10 Apr 2024	07 Mar 2024
Machine Age	kms	Client Info		249505	236893	229386
Oil Age	kms	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>75	55	23	32
Chromium	ppm	ASTM D5185(m)	>5	2	<1	1
Nickel	ppm	ASTM D5185(m)	>4	0	0	<1
Titanium	ppm	ASTM D5185(m)	>2	0	0	0
Silver	ppm	ASTM D5185(m)	>2	0	0	0
Aluminum	ppm	ASTM D5185(m)	>15	3	2	3
Lead	ppm	ASTM D5185(m)	>25	<1	0	<1
Copper	ppm	ASTM D5185(m)	>100	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>4	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1	<1	<1
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)		60	54	54
Manganese	ppm	ASTM D5185(m)		<1	<1	0
Magnesium	ppm	ASTM D5185(m)		974	880	851
Calcium	ppm	ASTM D5185(m)		1005	944	874
Phosphorus	ppm	ASTM D5185(m)		984	922	909
Zinc	ppm	ASTM D5185(m)		1192	1099	1071
Sulfur	ppm	ASTM D5185(m)		2310	2332	2367
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	6	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	4	6	4
Sodium	ppm	ASTM D5185(m)		5	2	5
Potassium	ppm	ASTM D5185(m)	>20	2	<1	3
Fuel	%	ASTM D7593*	>3.0	▲ 6.5	▲ 8.2	▲ 11.1
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>6	1.8	0.9	1.1
Nitration	Abs/cm	ASTM D7624*	>20	13.5	9.6	11.5
Sulfation	Abs/.1mm	ASTM D7415*	>30	27.0	20.9	22.4



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: WC0937238 Lab Number : 02641076 Unique Number : 5798615

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

Received : 11 Jun 2024 **Tested** : 12 Jun 2024 Diagnosed : 12 Jun 2024 - Wes Davis

Test Package : MOB 1 (Additional Tests: PercentFuel) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

CITY OF HAMILTON 2200 UPPER JAMES,, MOUNTAIN TRANSIT STOREROOM

MOUNT HOPE, ON CA LOR 1W0

Contact: Jeff Parr jeff.parr@hamilton.ca

T: (905)546-2424 F: (905)679-4502