

# **OIL ANALYSIS REPORT**

Silt

Sample Rating Trend

### NORMAL

### Area DOMTAR 321-702-1 [GTT224-445 DOMTAR] **TRANE DOMTAR 321-702-1**

Chiller Fluid **TRANE 0078 (--- GAL)** 

#### DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

#### Contamination

Insufficient sample was received to conduct all the routine laboratory tests. The water content is negligible.



Color		no image	no image
Bottom		no image	no image



## **OIL ANALYSIS REPORT**



Sample No. : GTT0003258 Received : 14 Jun 2024 4704 boul Bertrand Lab Number : 02642230 Tested : 24 Jun 2024 Rock Forest, QC Unique Number : 5799769 Diagnosed : 24 Jun 2024 - Bill Quesnel CA J1N 2B1 Test Package : IND 2 (Additional Tests: KV40) Contact: Service Manager To discuss this sample report, contact Customer Service at 1-905-847-9300 Ext 26. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Damages: Seller shall in no event be liable for special, incidental, or consequential damages, of a commercial nature, resulting from any cause.

Report Id: GTT0000040 [WCAMIS] 02642230 (Generated: 06/24/2024 12:18:57) Rev: 1

Contact/Location: Service Manager - GTT0000040 Page 2 of 2

Bridair Inc.

T:

F: