

# **OIL ANALYSIS REPORT**

# DOMTAR 136-767-1 [GTT224-445 DOMTAR] OTHER DOMTAR 136-767-1

Componer Chiller

Fluid REFRIGERATION OIL (POE) (--- GAL)

#### DIAGNOSIS

## Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

### Contamination

Insufficient sample was received to conduct all the routine laboratory tests. The water content is negligible.



Sample Rating Trend



WATER

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GTT0003257		
Sample Date		Client Info		31 May 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ATTENTION		
CONTAMINANTS		method	limit/base	current	history1	history2
ppm Water	ppm	ASTM D6304*	>200	<b>471</b>		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
SAMPLE IMAGES	\$	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image

Report Id: GTT0000040 [WCAMIS] 02642231 (Generated: 06/24/2024 12:18:26) Rev: 1



## **OIL ANALYSIS REPORT**



Sample No. : GTT0003257 Received : 14 Jun 2024 4704 boul Bertrand Lab Number : 02642231 Tested : 24 Jun 2024 Rock Forest, QC Unique Number : 5799770 Diagnosed : 24 Jun 2024 - Bill Quesnel CA J1N 2B1 Test Package : IND 2 (Additional Tests: KV40) Contact: Service Manager To discuss this sample report, contact Customer Service at 1-905-847-9300 Ext 26. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Damages: Seller shall in no event be liable for special, incidental, or consequential damages, of a commercial nature, resulting from any cause.

Report Id: GTT0000040 [WCAMIS] 02642231 (Generated: 06/24/2024 12:18:26) Rev: 1

Contact/Location: Service Manager - GTT0000040 Page 2 of 2

Bridair Inc.

T:

F: