


OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

KHS L2 INFEED FILLER

Gearbox

KLUBER KLUBEROIL 4 UH1-460 N (--- GAL)

DIAGNOSIS

Recommendation

We recommend that you drain the oil from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Aluminum and copper ppm levels are abnormal. Thrust washer and/or bearing/bushing wear is indicated.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

Additive levels indicate the addition of a different brand, or type of oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

.)		1		Jul2024	,	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0953983		
Sample Date		Client Info		02 Jul 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>200	76		
Chromium	ppm	ASTM D5185(m)	>15	1		
Nickel	ppm	ASTM D5185(m)	>15	1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>25	47		
Lead	ppm	ASTM D5185(m)	>100	17		
Copper	ppm	ASTM D5185(m)	>200	225		
Tin	ppm	ASTM D5185(m)	>25	5		
Antimony	ppm	ASTM D5185(m)	>5	0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		4		
Barium	ppm	ASTM D5185(m)		<1		
Molybdenum	ppm	ASTM D5185(m)		0		
Manganese	ppm	ASTM D5185(m)		2		
Magnesium	ppm	ASTM D5185(m)		<1		
Calcium	ppm	ASTM D5185(m)		253		
Phosphorus	ppm	ASTM D5185(m)		671		
Zinc	ppm	ASTM D5185(m)		671		
Sulfur	ppm	ASTM D5185(m)		755		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	47		
Sodium	ppm	ASTM D5185(m)		276		
Potassium	ppm	ASTM D5185(m)	>20	8		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory

Sample No. Lab Number : 02648225

: WC0953983

Unique Number : 5813777

Received **Tested**

: 16 Jul 2024 : 16 Jul 2024 Diagnosed

: 17 Jul 2024 - Kevin Marson

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 COCA COLA CANADA BOTTLING LTD. 15 WEST CREEK BLVD BRAMPTON, ON CA L6T 5T4

Contact: Chandan Ahuja cahuja@cokecanada.com T: (635)440-5087

Test Package : IND 1 To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.