

PROBLEM SUMMARY

Sample Rating Trend


WATER

GARDNER DENVER C-8 (S/N S521766)

Compressor

GARDNER DENVER AEON 9000 TH (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you follow the water drain-off procedure for this component, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to a high concentration of particles present in this sample.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL	
Water	%	ASTM D6304	>0.1	△ 0.125	△ 0.294	△ 0.329	
ppm Water	ppm	ASTM D6304	>1000	1250	2940	△ 3290	
Debris	scalar	*Visual	NONE	▲ MODER	▲ MODER	LIGHT	
Appearance	scalar	*Visual	NORML	LAYRD	▲ HAZY	▲ LAYRD	
Free Water	scalar	*Visual		2.0	<u>▲</u> 5.0	<u>^</u> 2.0	

Customer Id: WESLONWC Sample No.: WCI2288186 Lab Number: 04555167 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Water Drain-off	MISSED	Feb 05 2019	?	We advise that you follow the water drain-off procedure for this component, and use off-line filtration to improve the cleanliness of the system fluid.		
Resample	MISSED	Feb 05 2019	?	We recommend an early resample to monitor this condition.		
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.		

HISTORICAL DIAGNOSIS

25 May 2018 Diag: Jonathan Hester

WATER



We advise that you follow the water drain-off procedure for this component, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to a high concentration of particles present in this sample. All component wear rates are normal. Free water present. There is a light concentration of water present in the oil. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid.



24 Jan 2018 Diag: Doug Bogart

WAIER




We advise that you follow the water drain-off procedure for this component. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of particulates present in the oil. There is a light concentration of water present in the oil. Free water present. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



WATER

GARDNER DENVER C-8 (S/N S521766)

Compressor

GARDNER DENVER AEON 9000 TH (--- GAL)

DIAGNOSIS

Recommendation

We advise that you follow the water drain-off procedure for this component, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to a high concentration of particles present in this sample.

All component wear rates are normal.

Contamination

Free water present. There is a light concentration of water present in the oil. Moderate concentration of visible dirt/debris present in the oil.

Fluid Condition

The AN level is acceptable for this fluid.

L)		Ja	2018	May2018 Aug20	118	
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number		Client Info		WCI2288186	WCI2333178	WCI2317641
Sample Date		Client Info		28 Aug 2018	25 May 2018	24 Jan 2018
Machine Age	hrs	Client Info		9376	6782	4462
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	1	3	2
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m		0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	<1	<1	<1
Lead	ppm	ASTM D5185m	>25	1	2	<1
Copper	ppm	ASTM D5185m	>50	1	<1	<1
Tin	ppm	ASTM D5185m	>15	0	0	0
Antimony	ppm	ASTM D5185m		2	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m		2	<1	2
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	<1	0
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		1	0	0
Calcium	ppm	ASTM D5185m		<1	0	<1
Phosphorus	ppm	ASTM D5185m		708	694	655
Zinc	ppm	ASTM D5185m		3	2	<1
Sulfur	ppm	ASTM D5185m		44	11	19
CONTAMINANTS	3	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	<1	<1	<1
Sodium	ppm	ASTM D5185m		0	0	2
Potassium	ppm	ASTM D5185m	>20	<1	<1	4
Water	%	ASTM D6304	>0.1	<u> </u>	△ 0.294	△ 0.329
ppm Water	ppm	ASTM D6304	>1000	<u> </u>	2940	▲ 3290
FLUID CLEANLIN	IESS	method	limit/base	current	history 1	history 2
Particles >4μm		ASTM D7647	>10000			3871
Particles >6µm		ASTM D7647	>2500			2109
Particles >14µm		ASTM D7647	>320			▲ 359
Particles >21μm		ASTM D7647	>80			<u>▲</u> 121
Particles >38μm		ASTM D7647	>20			18
Particles >71μm		ASTM D7647	>4			1
Oil Cleanliness		ISO 4406 (c)	>20/18/15			△ 19/18/16
FLUID DEGRADA	ATION	method	limit/base	current	history 1	history 2

Acid Number (AN)


mg KOH/g ASTM D8045

0.532 Contact/Location: ROB WALLIN - WESLONWC

0.357



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number **Unique Number**

: WCI2288186

: 04555167 : 8339025

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 20 Sep 2018 : 21 Sep 2018 Diagnostician : Jonathan Hester

Test Package : IND 2 (Additional Tests: KF, PrtCount)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) 2290 CALLAHAN RD LONGVIEW, TX US 75607

Contact: ROB WALLIN rwallin@westlake.com

T: (903)242-7576 F: (903)758-9521