

OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

QUINCY QUINCY VACUUM PUMP 6

Vacuum Pump

TULCO LUBSOIL SYNTHETIC COMPRESS

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the

Fluid Condition

The condition of the oil is acceptable for the time in service.


OR 46 (GAL)			2017	May/2018 Jul2(10	
. ,	AATION					
SAMPLE INFORM	IATION	method	limit/base		history1	history2
Sample Number		Client Info		TO5010837	TO5010093	TO5007963
Sample Date		Client Info		23 Jul 2019	14 May 2018	03 Apr 2017
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION	1	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		18		18
Iron	ppm	ASTM D5185m	>500	<1	1	<1
Chromium	ppm	ASTM D5185m	>7	0	0	0
Nickel	ppm	ASTM D5185m		0	0	<1
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	<1	<1	<1
Lead	ppm	ASTM D5185m	>35	1	1	<1
Copper	ppm	ASTM D5185m	>50	<1	1	<1
Tin	ppm	ASTM D5185m	>5	0	0	0
Antimony	ppm	ASTM D5185m		2	1	<1
Vanadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	<1	0
Barium	ppm	ASTM D5185m		0	<1	0
Molybdenum	ppm	ASTM D5185m		<1	0	0
Manganese	ppm	ASTM D5185m		<1	<1	0
Magnesium	ppm	ASTM D5185m		2	2	<1
Calcium	ppm	ASTM D5185m		8	9	6
Phosphorus	ppm	ASTM D5185m	74	72	77	64
Zinc	ppm	ASTM D5185m		13	11	9
Sulfur	ppm	ASTM D5185m	1000	469	378	544
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	<1	<1	<1
Sodium	ppm	ASTM D5185m		38	41	32
Potassium	ppm	ASTM D5185m	>20	0	<1	0
FLUID DEGRADA	TION	method	limit/base	current	history1	history2

Acid Number (AN) mg KOH/g ASTM D8045 0.236

0.159



OIL ANALYSIS REPORT







Certificate 12367

Laboratory

Sample No. Lab Number

: 04761543

: TO5010837 Unique Number : 8674269

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received

Tested Diagnosed : 24 Jul 2019

: 25 Jul 2019

: 25 Jul 2019 - Jonathan Hester

Test Package : IND 2 (Additional Tests: KV100, PQ, VI)

To discuss this sample report, contact Customer Service at 1-800-237-1369. st - Denotes test methods that are outside of the ISO 17025 scope of accreditation. **DALLAS MORNING NEWS**

3900 W PLANO PKWY PLANO, TX US 75075

Contact: KENNY CLARK kclark@dallasnews.com

T: (214)977-6929 F: (214)977-6888

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) Report Id: DALPLATO [WUSCAR] 04761543 (Generated: 05/06/2024 15:01:29) Rev: 1

Contact/Location: KENNY CLARK - DALPLATO