


PROBLEM SUMMARY

Sample Rating Trend




Machine Id
VILTER A

Component
Compressor


Fluid
TULCO LUBSOIL LPG WI 100 (--- GAL)

COMPONENT CONDITION SUMMARY

▲ Particle Trend



▲ Silicon (ppm)



RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

Sample Status			ABNORMAL	ABNORMAL	ABNORMAL
Silicon	ppm	ASTM D5185m >25	▲ 71	▲ 110	▲ 67
Particles >4µm		ASTM D7647 >10000	▲ 69132	▲ 228588	▲ 88050
Particles >6µm		ASTM D7647 >2500	▲ 9887	▲ 100747	▲ 9274
Oil Cleanliness		ISO 4406 (c) >20/18/15	▲ 23/20/15	▲ 25/24/20	▲ 24/20/15

Customer Id: MELMELTX
Sample No.: TO50000129
Lab Number: 05569216
Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:
Don Baldrige +1
don.b505@comcast.net

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

09 Jun 2022 Diag: Jonathan Hester

DIRT



The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report



31 Jan 2022 Diag: Doug Bogart

DIRT



We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report



06 May 2021 Diag: Jonathan Hester


WATER



The filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The iron level is abnormal. Elemental level of silicon (Si) above normal indicating ingress of seal material. There is a moderate concentration of water present in the oil. The amount and size of particulates present in the system are acceptable. The oil viscosity is higher than normal. The AN level is acceptable for this fluid.

view report





DIRT



Machine Id
VILTER A

Component
Compressor

Fluid
TULCO LUBSOIL LPG WI 100 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORMATION	method	limit/base	current	history1	history2
Sample Number	Client Info		TO50000129	TO50000128	TO50000084
Sample Date	Client Info		09 Jun 2022	09 Jun 2022	31 Jan 2022
Machine Age	mths	Client Info	0	0	0
Oil Age	mths	Client Info	0	0	0
Oil Changed	Client Info		Filtered	Filtered	N/A
Sample Status			ABNORMAL	ABNORMAL	ABNORMAL

WEAR METALS	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m >50	1	18	1
Chromium	ppm	ASTM D5185m >10	0	0	0
Nickel	ppm	ASTM D5185m	<1	<1	1
Titanium	ppm	ASTM D5185m	0	0	0
Silver	ppm	ASTM D5185m	0	0	<1
Aluminum	ppm	ASTM D5185m >25	<1	<1	<1
Lead	ppm	ASTM D5185m >25	<1	<1	<1
Copper	ppm	ASTM D5185m >50	0	<1	<1
Tin	ppm	ASTM D5185m >15	1	2	<1
Antimony	ppm	ASTM D5185m	---	---	1
Vanadium	ppm	ASTM D5185m	0	0	0
Cadmium	ppm	ASTM D5185m	0	0	0






ADDITIVES	method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m 0	2	3	2
Barium	ppm	ASTM D5185m	0	0	0
Molybdenum	ppm	ASTM D5185m 0	<1	<1	<1
Manganese	ppm	ASTM D5185m	0	<1	0
Magnesium	ppm	ASTM D5185m 0	1	10	<1
Calcium	ppm	ASTM D5185m	<1	13	0
Phosphorus	ppm	ASTM D5185m 0	6	7	11
Zinc	ppm	ASTM D5185m 0	0	0	0
Sulfur	ppm	ASTM D5185m 0	4058	6757	3408

CONTAMINANTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m >25	▲ 71	▲ 110	▲ 67
Sodium	ppm	ASTM D5185m	0	1	<1
Potassium	ppm	ASTM D5185m >20	<1	<1	2
Water	%	ASTM D6304 >2.26	0.667	0.919	0.024
ppm Water	ppm	ASTM D6304 >22600	6670	9190	245.0

FLUID CLEANLINESS	method	limit/base	current	history1	history2
Particles >4µm	ASTM D7647	>10000	▲ 69132	▲ 228588	▲ 88050
Particles >6µm	ASTM D7647	>2500	▲ 9887	▲ 100747	▲ 9274
Particles >14µm	ASTM D7647	>320	256	▲ 8313	177
Particles >21µm	ASTM D7647	>80	47	▲ 2126	39
Particles >38µm	ASTM D7647	>20	1	▲ 36	2
Particles >71µm	ASTM D7647	>4	0	0	0
Oil Cleanliness	ISO 4406 (c)	>20/18/15	▲ 23/20/15	▲ 25/24/20	▲ 24/20/15

FLUID DEGRADATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.581	0.703	1.472


OIL ANALYSIS REPORT








VISUAL	method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	LIGHT
Yellow Metal	scalar	*Visual	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	LIGHT
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>2.26	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG

FLUID PROPERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	113	104	107
Visc @ 100°C	cSt	ASTM D445	19	17.4	18.86
Viscosity Index (VI)	Scale	ASTM D2270	189	184	197

SAMPLE IMAGES	method	limit/base	current	history1	history2
---------------	--------	------------	---------	----------	----------



GRAPHS



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : TO50000129 **Received** : 15 Jun 2022
Lab Number : 05569216 **Diagnosed** : 20 Jun 2022
Unique Number : 10013616 **Diagnostician** : Don Baldrige
Test Package : IND 2 (Additional Tests: KF, KV100, PrtCount, VI)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

MELISSA RENEWABLES
 3820 SAM RAYBURN HWY
 MELISSA, TX
 US 75454
 Contact: BILL PALMER
 bpalmer@morrowenergy.com

T: (972)529-8442

F: