

PROBLEM SUMMARY

Sample Rating Trend



LTI LADDER 4141

Component

Front Hydraulic System

AW HYDRAULIC OIL ISO 22 (--- GAL)

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS						
Sample Status				ABNORMAL	NORMAL	NORMAL
Debris	scalar	*Visual	NONE	▲ MODER	LIGHT	NONE

Customer Id: NEWNEWOH Sample No.: WC0672064 Lab Number: 05624967 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.

HISTORICAL DIAGNOSIS

18 Jul 2021 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



25 Sep 2020 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using MOB 2 test kits, this testkit includes Particle Count to determine the ISO cleanliness of the fluid.All component wear rates are normal. There is no indication of any contamination in the component(unconfirmed). The condition of the oil is acceptable for the time in service.

view report

29 Aug 2019 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using MOB 2 test kits, this testkit includes Particle Count to determine the ISO cleanliness of the fluid.All component wear rates are normal. There is no indication of any contamination in the component(unconfirmed). The condition of the oil is acceptable for the time in service.





OIL ANALYSIS REPORT

Sample Rating Trend



VIS DEBRIS



LTI LADDER 4141

Component

Front Hydraulic System

AW HYDRAULIC OIL ISO 22 (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Moderate concentration of visible dirt/debris present in the oil.


Fluid Condition

The condition of the oil is acceptable for the time in service.

		Sep2010 No	v2011 Nov2012 Nov2016	Sep2018 Aug2019 Sep2020 Jul20	21 Jun2022	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0672064	WC0591029	WC0499348
Sample Date		Client Info		19 Jun 2022	18 Jul 2021	25 Sep 2020
Machine Age	hrs	Client Info		1457	1434	0
Oil Age	hrs	Client Info		10868	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	3	<1	1
Chromium	ppm		>10	0	0	<1
Nickel	ppm	ASTM D5185m	>10	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver		ASTM D5185m		0	0	<1
Aluminum	ppm		>10	1	0	<1
	ppm		>10	_	0	0
Lead	ppm	ASTM D5185m		<1 4		
Copper	ppm	ASTM D5185m ASTM D5185m	>75	-	0	3
Tin	ppm		>10	0		0
Antimony	ppm	ASTM D5185m			0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	1	1	2
Barium	ppm	ASTM D5185m	5	0	0	0
Molybdenum	ppm	ASTM D5185m	5	1	<1	1
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m	25	<1	1	2
Calcium	ppm	ASTM D5185m	200	86	79	74
Phosphorus	ppm	ASTM D5185m	300	226	245	220
Zinc	ppm	ASTM D5185m	370	290	298	277
Sulfur	ppm	ASTM D5185m	2500	1328	1294	1122
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	6	3	4
Sodium	ppm	ASTM D5185m		3	3	5
Potassium	ppm	ASTM D5185m	>20	1	0	0
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	▲ MODER	LIGHT	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
		,				





OIL ANALYSIS REPORT




FLUID PROPERT	TES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	22	26.1	26.0	26.4
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
004000						

GRAPHS









Certificate L2367

Laboratory Sample No. Lab Number

: WC0672064 : 05624967 Unique Number : 10104474 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 23 Aug 2022 Diagnosed : 25 Aug 2022 Diagnostician : Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

NEWBURY FIRE 11111 KINSMAN RD NEWBURY, OH US 44065

Contact: FIRE CHIEF

Submitted By: RANDY PRICE

T: (440)564-2261 F: