

PROBLEM SUMMARY

Sample Rating Trend


ISO

AF01-2941

Component **Hydraulic System**

SUMMIT HYPAR 68 (450 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status			ABNORMAL					
Particles >4µm	ASTM D7647	>5000	<u> </u>					
Oil Cleanliness	ISO 4406 (c)	>19/17/14	21/17/11					

Customer Id: FLAMONNC Sample No.: WC0635716 Lab Number: 05632343 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS


Action	Status	Date	Done By	Description
Other Action (see Note)	DONE	Oct 12 2022	?	No recommended actions

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend







AF01-2941

Component

Hydraulic System

SUMMIT HYPAR 68 (450 GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


				Jun 2022		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0635716		
Sample Date		Client Info		07 Jun 2022		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		8		
Iron	ppm	ASTM D5185m	>20	7		
Chromium	ppm	ASTM D5185m	>20	<1		
Nickel	ppm	ASTM D5185m	>20	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		<1		
Aluminum	ppm	ASTM D5185m	>20	<1		
Lead	ppm	ASTM D5185m	>20	<1		
Copper	ppm	ASTM D5185m	>20	4		
Tin	ppm	ASTM D5185m	>20	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		0		
Calcium		ASTM D5185m		1		
Phosphorus	ppm	ASTM D5185m		522		
Zinc	ppm	ASTM D5185m		12		
Sulfur	ppm	ASTM D5185m		1704		
	ppm					
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	1		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	<1		
Water	%	ASTM D6304	>0.05	0.003		
ppm Water	ppm	ASTM D6304	>500	25.8		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>5000	<u> </u>		
Particles >6µm		ASTM D7647	>1300	1157		
Particles >14μm		ASTM D7647	>160	13		
Particles >21µm		ASTM D7647	>40	1		
Particles >38μm		ASTM D7647	>10	0		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u> </u>		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2

Page 3 of 4

0.16



OIL ANALYSIS REPORT





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: WC0635716 : 05632343

: 10116864

Received : 01 Sep 2022 Diagnosed Diagnostician

: 03 Sep 2022 : Don Baldridge Test Package : IND 2 (Additional Tests: KF, PQ)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

FLAKEBOARD ARAUCO - MDF

985 CORINTH RD MONCURE, NC

US

Contact: CHRISTOPHER JACKSON christopher.jackson@arauco.com

T:

Contact/Location: CHRISTOPHER JACKSON - FLAMONNC

F: