

# **PROBLEM SUMMARY**


# TEC 10K [12566100] **GARDNER DENVER S485666 - BHR RACKET STATION**

Component

Compressor



### **COMPONENT CONDITION SUMMARY**



### RECOMMENDATION

The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status				ABNORMAL						
Aluminum	ppm	ASTM D5185m	>25	<b>^</b> 69						

Customer Id: UCTOTSAI Sample No.: UCH05692598 Lab Number: 05692598 Test Package: IND 2 To manage this report scan the QR code To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

## RECOMMENDED ACTIONS

There are no recommended actions for this sample.

### HISTORICAL DIAGNOSIS




# **OIL ANALYSIS REPORT**

# TEC 10K [12566100] Machine Id GARDNER DENVER S485666 - BHR RACKET STATION

Component

Compressor



### DIAGNOSIS

### Recommendation

The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

### Wear

The aluminum level is abnormal. All other component wear rates are normal.

### Contamination

There is no indication of any contamination in the


#### **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Oct2022		
SAMPLE INFORM	IATION	method	limit/base		historyd	hiotom ()
	IATION		ilmit/base	current	history1	history2
Sample Number		Client Info		UCH05692598		
Sample Date		Client Info		28 Oct 2022		
Machine Age	hrs	Client Info		14993		
Oil Age	hrs	Client Info		2370		
Oil Changed		Client Info		Not Changd		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	22		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m		0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	<b>^</b> 69		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>50	<1		
Tin	ppm	ASTM D5185m	>15	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		0		
Phosphorus	ppm	ASTM D5185m		392		
Zinc	ppm	ASTM D5185m		0		
Sulfur	ppm	ASTM D5185m		697		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	1		
Sodium	ppm	ASTM D5185m		4		
Potassium	ppm	ASTM D5185m	>20	0		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.33		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual		NEG		
2:59:56) Rev: 1	odulai				ntact/Location: 3	



## **OIL ANALYSIS REPORT**





Certificate L2367

Laboratory Sample No. Lab Number

: UCH05692598 : 05692598 Unique Number : 10217171 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Nov 2022

Diagnosed : 15 Nov 2022 Diagnostician : Angela Borella **TOTAL EQUIPMENT COMPANY** 

200 SMILEY DR SAINT ALBANS, WV US 25177

Contact:

T:

F:

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)