


PROBLEM SUMMARY

Sample Rating Trend

ISO




Machine Id
MYCOM B

Component
Compressor


Fluid
TULCO LUBSOIL LPG WI 100 (--- GAL)

COMPONENT CONDITION SUMMARY

Particle Trend



Silicon (ppm)



RECOMMENDATION

The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

Sample Status			SEVERE	SEVERE	NORMAL
Silicon	ppm	ASTM D5185m >25	▲ 42	▲ 32	35
Particles >4µm		ASTM D7647 >10000	● 166203	● 199741	3738
Particles >6µm		ASTM D7647 >1300	● 75162	● 93775	1019
Particles >14µm		ASTM D7647 >320	● 8202	● 5545	86
Particles >21µm		ASTM D7647 >80	● 2669	● 820	17
Particles >38µm		ASTM D7647 >20	● 162	2	0
Particles >71µm		ASTM D7647 >4	▲ 7	0	0
Oil Cleanliness		ISO 4406 (c) >20/17/15	● 25/23/20	● 25/24/20	19/17/14

Customer Id: MELMELTX
Sample No.: TO50000122
Lab Number: 05708433
Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:
Angela Borella +1 800-237-1369
angela.borella@wearcheckusa.com

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

09 Jun 2022 Diag: Angela Borella

ISO



The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

view report



31 Jan 2022 Diag: Doug Bogart

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report



06 May 2021 Diag: Jonathan Hester

WATER



We advise that you follow the water drain-off procedure for this component, and use off-line filtration to improve the cleanliness of the system fluid. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. There is a moderate concentration of water present in the oil. The AN level is acceptable for this fluid.


view report



Machine Id
MYCOM B

Component
Compressor

Fluid
TULCO LUBSOIL LPG WI 100 (--- GAL)



DIAGNOSIS

Recommendation

The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number	Client Info			TO50000122	TO50000130	TO50000085
Sample Date	Client Info			01 Dec 2022	09 Jun 2022	31 Jan 2022
Machine Age	wks	Client Info		0	0	0
Oil Age	wks	Client Info		0	0	0
Oil Changed	Client Info			Filtered	Filtered	N/A
Sample Status				SEVERE	SEVERE	NORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	<1	0	<1
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m		0	<1	<1
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>25	0	<1	0
Lead	ppm	ASTM D5185m	>25	0	<1	<1
Copper	ppm	ASTM D5185m	>50	0	<1	<1
Tin	ppm	ASTM D5185m	>15	<1	1	<1
Antimony	ppm	ASTM D5185m		---	---	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0






ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0	3	3
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m	0	0	<1	<1
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m	0	2	2	<1
Calcium	ppm	ASTM D5185m		0	3	<1
Phosphorus	ppm	ASTM D5185m	0	37	27	17
Zinc	ppm	ASTM D5185m	0	5	0	0
Sulfur	ppm	ASTM D5185m	0	987	2528	946

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	▲ 42	▲ 32	35
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	0	<1	1
Water	%	ASTM D6304	>2.26	0.208	0.297	0.685
ppm Water	ppm	ASTM D6304	>22600	2086.3	2971.3	6851.6

FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	● 166203	● 199741	3738
Particles >6µm		ASTM D7647	>1300	● 75162	● 93775	1019
Particles >14µm		ASTM D7647	>320	● 8202	● 5545	86
Particles >21µm		ASTM D7647	>80	● 2669	● 820	17
Particles >38µm		ASTM D7647	>20	● 162	2	0
Particles >71µm		ASTM D7647	>4	▲ 7	0	0
Oil Cleanliness		ISO 4406 (c)	>20/17/15	● 25/23/20	● 25/24/20	19/17/14

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.68	0.259	0.338

OIL ANALYSIS REPORT








VISUAL	method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>2.26	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG

FLUID PROPERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	113	106	104
Visc @ 100°C	cSt	ASTM D445	19	18.3	17.6
Viscosity Index (VI)	Scale	ASTM D2270	189	192	186

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					

GRAPHS



Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : TO50000122 **Received** : 05 Dec 2022
Lab Number : 05708433 **Diagnosed** : 06 Dec 2022
Unique Number : 10243008 **Diagnostician** : Angela Borella
Test Package : IND 2 (Additional Tests: KF, KV100, PrtCount, VI)

MELISSA RENEWABLES
 3820 SAM RAYBURN HWY
 MELISSA, TX
 US 75454
 Contact: BILL PALMER
 bpalmer@morrowenergy.com
 T: (972)529-8442
 F:

To discuss this sample report, contact Customer Service at 1-800-237-1369.
 * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)