

PROBLEM SUMMARY


{UNASSIGNED} Machine Id PALFINGER 100426578

Hydraulic System
Fluid

NOT GIVEN (150 GAL)

Sample Rating Trend ISO October 2

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor. (Customer Sample Comment: 150 gallon. 2878 hours)

PROBLEMATIC TEST RESULTS									
Sample Status			ABNORMAL						
Particles >4µm	ASTM D7647	>5000	A 84017						
Particles >6µm	ASTM D7647	>1300	10495						
Oil Cleanliness	ISO 4406 (c)	>19/17/14	24/21/13						

Customer Id: PALJACNJ Sample No.: WC0695493 Lab Number: 05721934 Test Package: CONST



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

YUNASSIGNED | Machine Id | PALFINGER 100426578

Component

Hydraulic System

NOT GIVEN (150 GAL)

Sample Rating Trend



DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor. (Customer Sample Comment: 150 gallon. 2878 hours)

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in


				Oct2022		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0695493		
Sample Date		Client Info		05 Oct 2022		
Machine Age	hrs	Client Info		2878		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	5		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>10	<1		
Lead	ppm	ASTM D5185m	>10	0		
Copper	ppm	ASTM D5185m	>75	2		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		<1		
Molybdenum	ppm	ASTM D5185m		1		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		4		
Calcium	ppm	ASTM D5185m		60		
Phosphorus	ppm	ASTM D5185m		502		
Zinc	ppm	ASTM D5185m		276		
Sulfur	ppm	ASTM D5185m		1426		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	<1		
Sodium	ppm	ASTM D5185m		2		
Potassium	ppm	ASTM D5185m	>20	0		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<u> </u>		
Particles >6µm		ASTM D7647	>1300	<u> </u>		
Particles >14µm		ASTM D7647	>160	65		
Particles >21µm		ASTM D7647	>40	8		
Particles >38μm		ASTM D7647	>10	0		
Particles >71μm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u>4</u> 24/21/13		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	та КОЦ/а	VCTM DOUVE		0.26		

Acid Number (AN) mg KOH/g ASTM D8045

0.36



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number

Unique Number Test Package : CONST

: WC0695493 : 05721934 : 10266515

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 20 Dec 2022 Diagnostician

: 21 Dec 2022 : Angela Borella

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

JACKSON, NJ US 08527 Contact: DON DRESS

PALFINGER - BRANCH 410

632 CEDAR SWAMP RD

d.dress@palfinger.com

T: F:

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)