

PROBLEM SUMMARY

Sample Rating Trend

ISO


PALFINGER 100490425

Component

Hydraulic System

AW HYDRAULIC OIL ISO 32 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC T	EST RESULTS			
Sample Status			ABNORMAL	
Particles >4µm	ASTM D7647	>5000	<u> </u>	
Oil Cleanliness	ISO 4406 (c)	>19/17/14	21/16/11	

Customer Id: PALJACNJ Sample No.: WC0695624 Lab Number: 05721947 Test Package: CONST

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend ISO

PALFINGER 100490425

Hydraulic System

AW HYDRAULIC OIL ISO 32 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Dec2022		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0695624		
Sample Date		Client Info		05 Dec 2022		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	1		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>10	0		
Lead	ppm	ASTM D5185m	>10	0		
Copper	ppm	ASTM D5185m	>75	2		
Tin	ppm	ASTM D5185m	>10	 <1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0		
Barium	ppm	ASTM D5185m	5	<1		
Molybdenum	ppm	ASTM D5185m	5	<1		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	25	4		
Calcium	ppm	ASTM D5185m	200	61		
Phosphorus	ppm	ASTM D5185m	300	251		
Zinc	ppm	ASTM D5185m	370	324		
Sulfur	ppm	ASTM D5185m	2500	982		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	<1		
Sodium	ppm	ASTM D5185m	00	<1		
Potassium	ppm	ASTM D5185m	>20	0		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>5000	<u> </u>		
Particles >6µm		ASTM D7647	>1300	602		
Particles >14µm		ASTM D7647	>160	15		
Particles >21µm		ASTM D7647	>40	5		
Particles >38µm		ASTM D7647	>10	0		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u>21/16/11</u>		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
					,	,



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number

Unique Number

: 05721947 : 10266528

: WC0695624 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 20 Dec 2022 Diagnosed Diagnostician

: 21 Dec 2022 : Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

PALFINGER - BRANCH 410 632 CEDAR SWAMP RD

JACKSON, NJ US 08527

Contact: DON DRESS d.dress@palfinger.com

T: F: