


# COMPONENT CONDITION SUMMARY



# RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status			ABNORMAL	ATTENTION	ABNORMAL			
Particles >4µm	ASTM D7647	>1300	<u> </u>	<b>1</b> 705				
Particles >6µm	ASTM D7647	>320	<u> </u>	<b>4</b> 346				
Particles >14µm	ASTM D7647	>40	<u> </u>	27				
Oil Cleanliness	ISO 4406 (c)	>17/15/12	<b>  19/17/13</b>	🔺 18/16/12				

Customer Id: FLAMONNC Sample No.: WC0764197 Lab Number: 05758237 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com ISO

RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description	
Change Filter			?	We recommend you service the filters on this component.	

# **HISTORICAL DIAGNOSIS**



07 Jul 2021 Diag: Doug Bogart

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

# view report

view report

### 18 May 2016 Diag: Jonathan Hester



We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample. The copper level is abnormal. All other component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

13 Jan 2016 Diag: Doug Bogart

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.







# **OIL ANALYSIS REPORT**

# Area ENERGY CROSS COMPANY 0340 PP02

Componen **Hydraulic System** 

KLUBER SUMMIT HYSYN FG 46 (--- GAL)

# DIAGNOSIS

# Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

# Wear

All component wear rates are normal.

### Contamination

There is a high amount of particulates present in the oil.


### Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.






# **OIL ANALYSIS REPORT**









FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.093	0.107	0.377
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	🔺 MODER
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	TIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	46	42.5	43.0	44.96
SAMPLE IMAGES	S	method	limit/base	current	history1	history2

Color

Bottom







Contact/Location: CHRISTOPHER JACKSON - FLAMONNC