


PROBLEM SUMMARY


CURING Machine Id [CURING] PRESS_017 HYDRAULIC SUMP PRESS 17

Hydraulic System

NOT GIVEN (500 LTR)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status			ABNORMAL	NORMAL					
Particles >4µm	ASTM D7647	>5000	△ 36017	2998					
Particles >6µm	ASTM D7647	>1300	3954	442					
Oil Cleanliness	ISO 4406 (c)	>19/17/14	22/19/13	19/16/12					

Customer Id: NOKDAY Sample No.: WC0755639 Lab Number: 05759398 Test Package: PLANT

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component if applicable.

HISTORICAL DIAGNOSIS

11 May 2021 Diag: Jonathan Hester

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.






OIL ANALYSIS REPORT

CURING [CURING] PRESS_017 HYDRAULIC SUMP PRESS 17

Hydraulic System

NOT GIVEN (500 LTR)





DIAGNOSIS

Recommendation

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

			May2021	Feb 2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0755639	WC0574459	
Sample Date		Client Info		05 Feb 2023	11 May 2021	
Machine Age	hrs	Client Info		0	0	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		N/A	N/A	
Sample Status				ABNORMAL	NORMAL	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	10	<1	
Chromium	ppm	ASTM D5185m	>20	1	<1	
Nickel	ppm	ASTM D5185m	>20	0	0	
Titanium	ppm	ASTM D5185m		0	0	
Silver	ppm	ASTM D5185m		0	<1	
Aluminum	ppm	ASTM D5185m	>20	0	0	
Lead	ppm	ASTM D5185m	>20	0	0	
Copper	ppm	ASTM D5185m	>20	6	7	
Tin	ppm	ASTM D5185m	>20	0	0	
Antimony	ppm	ASTM D5185m			0	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	<1	
Barium	ppm	ASTM D5185m		0	0	
Molybdenum	ppm	ASTM D5185m		0	0	
Manganese	ppm	ASTM D5185m		<1	0	
Magnesium	ppm	ASTM D5185m		0	0	
Calcium	ppm	ASTM D5185m		102	107	
Phosphorus	ppm	ASTM D5185m		428	458	
Zinc	ppm	ASTM D5185m		56	52	
Sulfur	ppm	ASTM D5185m		2241	1854	
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	1	<1	
Sodium	ppm	ASTM D5185m		2	0	
Potassium	ppm	ASTM D5185m	>20	0	0	
Water	%	ASTM D6304	>0.05	NEG	NEG	
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	4 36017	2998	
Particles >6µm		ASTM D7647	>1300	<u></u> 3954	442	
Particles >14µm		ASTM D7647	>160	42	21	
Particles >21µm		ASTM D7647	>40	10	4	
Particles >38µm		ASTM D7647	>10	1	0	
Particles >71µm		ASTM D7647	>3	0	0	
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u>22/19/13</u>	19/16/12	
FLUID DEGRADA	NOITA	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.127	0.199	



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number **Unique Number**

: WC0755639 : 05759398 : 10324005 Test Package : PLANT

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 06 Feb 2023 Recieved

Diagnostician

Diagnosed : 07 Feb 2023 : Jonathan Hester **NOKIAN TYRES US OPERATIONS LLC** 520 NOKIAN TYRES DRIVE

DAYTON, TN

US 37321 Contact: CHRIS NAPIER

christopher.napier@nokiantyres.com

T: (423)457-3121

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)