

PROBLEM SUMMARY

Area **14**

HANSENS WTG-1403 (S/N EH806A-003-LM0042)

Wind Turbine Gearbox

FUCHS RENOLIN UNISYN CKC ISO 320 (340 LTR)

COMPONENT CONDITION SUMMARY



No relevant graphs to display

RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

PROBLEMATIC TEST RESULTS						
Sample Status				ABNORMAL	NORMAL	NORMAL
Silt	scalar	*Visual	NONE	▲ HEAVY	NONE	NONE

Customer Id: ENEFRA **Sample No.:** WC0804456 Lab Number: 05857921 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.

HISTORICAL DIAGNOSIS

06 Mar 2023 Diag: Aaron Black

NORMAL



Resample at the next service interval to monitor. Analytical Ferrography: Results indicate normal operation, with typical amounts of ferrous rubbing wear and contamination, and only a single sliding wear particle is present but has no notable issue associated with it.All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



04 Feb 2022 Diag: Jonathan Hester

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

03 Mar 2021 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The water content is negligible. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.






OIL ANALYSIS REPORT

Area **14**

HANSENS WTG-1403 (S/N EH806A-003-LM0042)

Wind Turbine Gearbox

FUCHS RENOLIN UNISYN CKC ISO 320 (340 LTR)





DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

Wear

All component wear rates are normal.

Contamination

There is a high amount of visible silt present in the sample.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

		vlay2015 Au	g2016 May2017 Jul2	2018 Oct2019 Mar2021	Mar2023	
SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0804456	WC0804450	WC05504485
Sample Date		Client Info		06 Mar 2023	06 Mar 2023	04 Feb 2022
Machine Age	mths	Client Info		101	37	32
Oil Age	mths	Client Info		101	37	0
Oil Changed		Client Info		Not Changd	Not Changd	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184	>50	9	13	17
Iron	ppm	ASTM D5185m	>65	19	16	13
Chromium	ppm	ASTM D5185m	>3	<1	<1	0
Nickel	ppm	ASTM D5185m	>3	0	0	0
Titanium	ppm	ASTM D5185m	>10	0	0	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>10	<1	<1	0
	ppm	ASTM D5185m	>5	<1	0	0
Copper	ppm	ASTM D5185m	>10	0	0	0
Tin	ppm	ASTM D5185m	>10	0	0	0
Antimony	ppm	ASTM D5185m	>5			
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	25	2	<1	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		0	1	0
Calcium	ppm	ASTM D5185m	17	6	18	20
Phosphorus	ppm	ASTM D5185m	200	344	242	249
Zinc	ppm	ASTM D5185m		23	6	0
Sulfur	ppm	ASTM D5185m	5000	6291	5186	4168
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1	<1	0
Sodium	ppm	ASTM D5185m		3	6	4
Potassium	ppm	ASTM D5185m	>20	1	2	0
Water	%	ASTM D6304	>0.03	0.015	0.014	0.013
ppm Water	ppm	ASTM D6304	>300	158.0	148.8	132.5
FLUID CLEANLINE	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647			371	522
Particles >6µm		ASTM D7647	>5000		72	144
Particles >14µm		ASTM D7647	>640		7	14
Particles >21µm		ASTM D7647	>160		2	4
Particles >38µm		ASTM D7647	>40		0	0
Particles >71µm		ASTM D7647	>10		0	0
Oil Cleanliness		ISO 4406 (c)	>/19/16		16/13/10	16/14/11
		(*)				•



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: 05857921 : 10492386

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 26 May 2023 : WC0804456 Diagnosed

: 30 May 2023 Diagnostician : Don Baldridge

Test Package: IND 2 (Additional Tests: KF, PQ, PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) **ENERGIA EOLICA**

STA ANA KM25 CARRETERA AL SUR, A 1KM DEL CRUCE FRANCISCO MORAZAN, ZZ

HN Contact: SANTOS DEL CID

sdelcid@dencmi.com

T: x:

F: x:

Contact/Location: SANTOS DEL CID - ENEFRA