

PROBLEM SUMMARY

Sample Rating Trend

ISO

FINISHING/1255

1255-003-1900 - HPU 1255-003-1900

Component


Hydraulic System

PETRO CANADA HYDREX AW 68 (--- GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TES	ST RESULTS				
Sample Status			ABNORMAL	ABNORMAL	ATTENTION
Particles >4µm	ASTM D7647	>5000	<u> </u>	<u>14296</u>	▲ 8030
Particles >6µm	ASTM D7647	>1300	1762	<u>^</u> 2684	833
Oil Cleanliness	ISO 4406 (c)	>19/17/14	21/18/14	A 21/19/15	A 20/17/12

Customer Id: CONMUSAL Sample No.: KFS0003848 Lab Number: 05899863 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.
Resample			?	We recommend an early resample to monitor this condition.
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

HISTORICAL DIAGNOSIS

21 Oct 2022 Diag: Don Baldridge

ISO



We recommend you service the filters on this component. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



19 Aug 2022 Diag: Angela Borella

ISO



No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

12 May 2022 Diag: Angela Borella

ISO



We recommend you service the filters on this component. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.






OIL ANALYSIS REPORT

FINISHING/1255

1255-003-1900 - HPU 1255-003-1900

Hydraulic System

PETRO CANADA HYDREX AW 68 (--- GAL)





DIAGNOSIS

Recommendation

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

		Jun2021	Apr2022 May2022	. Aug2022 Oct2022	Jul2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KFS0003848	KFS0002244	KFS0001877
Sample Date		Client Info		14 Jul 2023	21 Oct 2022	19 Aug 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ATTENTION
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	<1	0	<1
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	0	0	0
Lead	ppm	ASTM D5185m	>20	0	0	<1
Copper	ppm	ASTM D5185m	>20	<1	<1	<1
Tin	ppm	ASTM D5185m	>20	0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0	0	0
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	0	0	0	0
Manganese	ppm	ASTM D5185m	0	0	0	0
Magnesium	ppm	ASTM D5185m	0	0	0	0
Calcium	ppm	ASTM D5185m	50	56	52	56
Phosphorus	ppm	ASTM D5185m	330	373	340	342
Zinc	ppm	ASTM D5185m	430	487	400	461
Sulfur	ppm	ASTM D5185m	760	1072	978	894
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	0	6	0
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	<1	0	<1
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>5000	<u> </u>	▲ 14296	▲ 8030
Particles >6µm		ASTM D7647	>1300	<u> </u>	<u>^</u> 2684	833
Particles >14μm		ASTM D7647	>160	120	<u> </u>	32
Particles >21µm		ASTM D7647	>40	41	<u>▲</u> 55	7
Particles >38µm		ASTM D7647	>10	3	2	1
Particles >71µm		ASTM D7647	>3	1	0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u>^</u> 21/18/14	<u>\$\text{\Delta}\$ 21/19/15</u>	<u>△</u> 20/17/12
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.60	0.42	0.41	0.39



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** Test Package

: KFS0003848

: 05899863 : 10561219 : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 17 Jul 2023 Received Diagnosed : 18 Jul 2023 : Wes Davis Diagnostician

4805 SECOND STREET MUSCLE SHOALS, AL US 35661

CONSTELLIUM

Contact: Randy Nichols randall.nichols@constellium.com

T: (256)386-6956

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: