


# **PROBLEM SUMMARY**


# Area [603921062 SDR] **BRINE DIS PUMP 3 (S/N 20049414)**

Component Pump Fluid

ISO 68 (--- GAL)



#### **COMPONENT CONDITION SUMMARY**



#### RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS											
Sample Status			ATTENTION								
Visc @ 40°C	cSt	ASTM D445	68.0	<b>A</b> 81.3							

Customer Id: MARSCHI **Sample No.:** WC0605523 Lab Number: 05901415 Test Package: IND 2 To manage this report scan the QR code To discuss the diagnosis or test data: Don Baldridge +1 don.b505@comcast.net To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

### RECOMMENDED ACTIONS

There are no recommended actions for this sample.

### HISTORICAL DIAGNOSIS



# **OIL ANALYSIS REPORT**

## Sample Rating Trend

### **VISCOSITY**



# Area [603921062 SDR] BRINE DIS PUMP 3 (S/N 20049414)

ISO 68 (--- GAL)

Pump Fluid

## DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

#### Contamination

There is no indication of any contamination in the

#### Fluid Condition


The oil viscosity is higher than normal. Confirm oil type. The AN level is acceptable for this fluid.

				Jun 2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0605523		
Sample Date		Client Info		22 Jun 2023		
Machine Age	mls	Client Info		0		
Oil Age	mls	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				ATTENTION		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>90	0		
Chromium	ppm	ASTM D5185m	>5	0		
Nickel	ppm	ASTM D5185m	>5	0		
Titanium	ppm	ASTM D5185m	>3	0		
Silver	ppm	ASTM D5185m	>3	0		
Aluminum	ppm	ASTM D5185m	>7	1		
Lead	ppm	ASTM D5185m	>12	<1		
Copper	ppm	ASTM D5185m	>30	<1		
Tin	ppm	ASTM D5185m	>9	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
	le le					
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		<1		
Calcium	ppm	ASTM D5185m		0		
Phosphorus	ppm	ASTM D5185m		71		
Zinc	ppm	ASTM D5185m		2		
Sulfur	ppm	ASTM D5185m		1179		
CONTAMINANTS	<b>,</b>	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>60	<1		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	1		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.29		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual		NEG		
Free Water	scalar	*Visual		NEG		

Contact/Location: TONY FIORE - MARSCHI



# **OIL ANALYSIS REPORT**







Certificate L2367

Laboratory Sample No. Lab Number

: WC0605523 : 05901415 Unique Number : 10562771

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 18 Jul 2023 Diagnosed : 20 Jul 2023 Diagnostician : Don Baldridge

Test Package : IND 2 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) MARS CHOCOLATE

2019 NORTH OAK PARK CHICAGO, IL US 60707

Contact: TONY FIORE tony.fiore@effem.com T: (773)745-2279

Contact/Location: TONY FIORE - MARSCHI