
Sullivan Palatek

PROBLEM SUMMARY


AEON 9000 SP Machine Id COMPAIR CD10015649001

Component

Compressor



COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you follow the water drain-off procedure for this component. The filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status				ATTENTION					
Water	%	ASTM D6304	>0.1	△ 0.113					
ppm Water	ppm	ASTM D6304	>1000	<u> </u>					
Emulsified Water	scalar	*Visual	>0.1	0.2%					
Free Water	scalar	*Visual		1.0					

Customer Id: UCJEMWES Sample No.: UCS05922297 Lab Number: 05922297 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description	
Water Drain-off			?	We advise that you follow the water drain-off procedure for this component.	
Resample			?	We recommend an early resample to monitor this condition.	

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

AEON 9000 SP **COMPAIR CD10015649001**

Component

Compressor



DIAGNOSIS

Recommendation

We advise that you follow the water drain-off procedure for this component. The filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

Moderate concentration of visible dirt/debris present in the oil. There is a light concentration of water present in the oil. Free water present.

Fluid Condition

The AN level is acceptable for this fluid.

SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UCS05922297		
Sample Date		Client Info		03 Aug 2023		
Machine Age	hrs	Client Info		21093		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				ATTENTION		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	1		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m		<1		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	2		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>50	0		
Tin	ppm	ASTM D5185m	>15	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	0	0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	0	<1		
Calcium	ppm	ASTM D5185m	0	0		
Phosphorus	ppm	ASTM D5185m	800	794		
Zinc	ppm	ASTM D5185m	0	0		
Sulfur	ppm	ASTM D5185m	0	8		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	<1		
Sodium	ppm	ASTM D5185m		<1		
Potassium	ppm	ASTM D5185m	>20	1		
Water	%	ASTM D6304	>0.1	<u> </u>		
ppm Water	ppm	ASTM D6304	>1000	<u> </u>		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2


0.27

Acid Number (AN)

mg KOH/g ASTM D8045 .170



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number Unique Number

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : UCS05922297

: 05922297 : 10602244

Received : 11 Aug 2023 Diagnosed : 14 Aug 2023 Diagnostician : Don Baldridge

Test Package : IND 2 (Additional Tests: KF) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) JEMCO-MAXAIR

WEST FARGO, ND US 58078 Contact: DALE K

dalek@jemco-maxair.com

T: (701)281-0362

F: x: Contact/Location: DALE K - UCJEMWES