

PROBLEM SUMMARY

Sample Rating Trend

DIRT


A

TWIN_U4 TWIN_U4_M4

Non-Drive End Bearing

ROYAL PURPLE SYNFILM GT 32 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC T	PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL					
Silicon	ppm	ASTM D5185m	>15	43					

Customer Id: ENEASTPA
Sample No.: RP0031947
Lab Number: 05922860
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Don Baldridge +1
don.b505@comcast.net

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend

DIRT

TWIN_U4 TWIN_U4_M4

Non-Drive End Bearing

ROYAL PURPLE SYNFILM GT 32 (--- GAL)

Recommendation

DIAGNOSIS

No corrective action is recommended at this time. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

Elemental level of silicon (Si) above normal indicating ingress of dirt/seal material.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Aug ² 023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		RP0031947		
Sample Date		Client Info		09 Aug 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>20	<1		
Chromium	ppm	ASTM D5185m	>20	0		
Nickel	ppm	ASTM D5185m	>20	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>20	2		
Lead	ppm	ASTM D5185m	>20	1		
Copper	ppm	ASTM D5185m	>20	20		
Tin	ppm	ASTM D5185m	>20	2		
Vanadium	ppm	ASTM D5185m		- <1		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		84		
Calcium	ppm	ASTM D5185m		0		
Phosphorus	ppm	ASTM D5185m		6		
Zinc	ppm	ASTM D5185m		3		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	43		
Sodium	ppm	ASTM D5185m		2		
Potassium	ppm	ASTM D5185m	>20	0		
Water	%	ASTM D6304	>2	0.032		
opm Water	ppm	ASTM D6304		321.5		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.349		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	LIGHT		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odar	ooole"	*\/;aal	NODM	NODMI		

NORML

>2

scalar

scalar

*Visual

*Visual

scalar *Visual

NORML

NEG

NEG


Odor

Emulsified Water

QUITA MORGAN - ENEASTPA



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: RP0031947 : 05922860 : 10602807 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 11 Aug 2023 : 14 Aug 2023 Diagnosed

Diagnostician : Don Baldridge

ENERGY TRANSFER - TWIN OAKS 144 CONCHESTER HIGHWAY

ASTON, PA US 19014

Contact: QUITA MORGAN

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (610)220-8386 F: