


PROBLEM SUMMARY

Area Martinsville [Martinsville] Oil - Port Genset Component Port Genset Fluid MOBIL 15W40 (7 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. (Customer Sample Comment: George Willis)

PROBLEMATIC TEST RESULTS							
Sample Status			ATTENTION	NORMAL	ATTENTION		
Visc @ 100°C	cSt	ASTM D445	🔺 12.3	14.5	12.3		


Customer Id: MARCAT Sample No.: WC0769133 Lab Number: 05927461 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com



RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		

HISTORICAL DIAGNOSIS



10 Jul 2023 Diag: Don Baldridge

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



view report

13 Jun 2023 Diag: Jonathan Hester



No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.


15 May 2023 Diag: Don Baldridge





Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.







OIL ANALYSIS REPORT

Area Martinsville [Martinsville] Oil - Port Genset

Port Genset Fluid MOBIL 15W40 (7 GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. (Customer Sample Comment: George Willis)

Wear

All component wear rates are normal.

Contamination

Fuel content negligible. There is no indication of any contamination in the oil.

Fluid Condition


The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.




SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0769133	WC0769179	WC0719195
Sample Date		Client Info		08 Aug 2023	10 Jul 2023	13 Jun 2023
Machine Age	hrs	Client Info		4189	3795	3488
Oil Age	hrs	Client Info		446	55	258
Oil Changed		Client Info		Changed	N/A	Not Changd
Sample Status				ATTENTION	NORMAL	ATTENTION
CONTAMINATION	N	method	limit/base	current	history1	history2
Glycol		WC Method		NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>25	8	2	5
Chromium	ppm	ASTM D5185m	>5	<1	<1	<1
Nickel	ppm	ASTM D5185m	>5	0	<1	0
Titanium	ppm	ASTM D5185m		<1	<1	<1
Silver	ppm	ASTM D5185m	>5	0	0	0
Aluminum	ppm	ASTM D5185m	>10	2	<1	<1
Lead	ppm	ASTM D5185m	>10	<1	<1	0
Copper	ppm	ASTM D5185m	>20	1	<1	2
Tin	ppm	ASTM D5185m	>5	<1	<1	<1
Vanadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		50	85	73
Barium	ppm	ASTM D5185m		0	2	0
Molybdenum	ppm	ASTM D5185m		71	68	72
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		1389	1264	1440
Calcium	ppm	ASTM D5185m		1301	1217	1407
Phosphorus	ppm	ASTM D5185m		970	929	1039
Zinc	ppm	ASTM D5185m		1185	1105	1251
Sulfur	ppm	ASTM D5185m		3773	3280	4109
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	4	6	3
Sodium	ppm	ASTM D5185m	>118	0	0	2
Potassium	ppm	ASTM D5185m	>20	0	1	1
Fuel	%	ASTM D3524	>4.0	0.3	<1.0	0.5
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844		0.3	0.1	0.2
Nitration	Abs/cm	*ASTM D7624	>20	8.4	5.5	7.0
Sulfation	Abs/.1mm	*ASTM D7415	>30	19.9	18.2	20.3
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	15.4	13.2	16.1
Base Number (BN)	mg KOH/g	ASTM D2896		12.60	11.92	9.80



OIL ANALYSIS REPORT






VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445		12.3	14.5	1 2.3
GRAPHS						


Ferrous Alloys

Non-ferrous Metals

400

350 300





Test Package : IND 2 (Additional Tests: FuelDilution, PercentFuel) Certificate L2367 cagumbert@marathonpetroleum.com To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: MARCAT [WUSCAR] 05927461 (Generated: 08/21/2023 16:00:44) Rev: 1

Submitted By: M/V MARTINSVILLE

Page 4 of 4

F: x:

T: (606)585-3950