



COMPONENT CONDITION SUMMARY



🔺 Viscosity @ 100°C



RECOMMENDATION

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Sample Status				ABNORMAL	ABNORMAL	
Fuel	%	ASTM D3524	>5	5.3	4 .1	
Visc @ 100°C	cSt	ASTM D445	15.4	11.8	11.6	

Customer Id: SCHPLA Sample No.: SBP0005088 Lab Number: 05928658 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED AC	TIONS			
Action	Status	Date	Done By	Description
Resample			?	We recommend an early resample to monitor this condition.

HISTORICAL DIAGNOSIS

FUEL



23 Jan 2023 Diag: Don Baldridge

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Light fuel dilution occurring. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil.





OIL ANALYSIS REPORT

Sample Rating Trend

FUEL

Area SCHTRUCK 6198 [SCHTRUCK]

Component **Diesel Engine**

Fluid PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

IAL)			Jan2023	Aug2023		
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		SBP0005088	SBP0002536	
Sample Date		Client Info		15 Aug 2023	23 Jan 2023	
Machine Age	mls	Client Info		310794	286679	
Oil Age	mls	Client Info		24115	22764	
Oil Changed		Client Info		Changed	Changed	
Sample Status				ABNORMAL	ABNORMAL	
CONTAMINATION	V	method	limit/base	current	history1	history2
Glycol		WC Method		NEG	NEG	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	29	19	
Chromium	ppm	ASTM D5185m	>5	2	1	
Nickel	ppm	ASTM D5185m	>2	0	<1	
Titanium	ppm	ASTM D5185m		<1	0	
Silver	ppm	ASTM D5185m	>3	<1	0	
Aluminum	ppm	ASTM D5185m	>30	2	2	
Lead	ppm	ASTM D5185m	>30	5	4	
Copper	ppm	ASTM D5185m	>150	2	1	
Tin	ppm	ASTM D5185m	>5	1	2	
Vanadium	ppm	ASTM D5185m		<1	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	3	35	
Barium	ppm	ASTM D5185m	0	0	0	
Molybdenum	ppm	ASTM D5185m	60	56	45	
Manganese	ppm	ASTM D5185m	0	<1	<1	
Magnesium	ppm	ASTM D5185m	1010	913	506	
Calcium	ppm	ASTM D5185m	1070	1135	1692	
Phosphorus	ppm	ASTM D5185m	1150	942	734	
Zinc	ppm	ASTM D5185m	1270	1146	912	
Sulfur	ppm	ASTM D5185m	2060	3314	2670	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	3	6	
Sodium	ppm	ASTM D5185m		7	6	
Potassium	ppm	ASTM D5185m	>20	4	<1	
Fuel	%	ASTM D3524	>5	4 5.3	4 .1	
		method	limit/base	current	history1	history2
INFRA-RED		method				
	%	*ASTM D7844	>3	0.6	0.7	
Soot %	% Abs/cm			0.6 8.3	0.7 9.4	
Soot % Nitration		*ASTM D7844	>3			
Soot % Nitration	Abs/cm Abs/.1mm	*ASTM D7844 *ASTM D7624	>3 >20	8.3	9.4	
Soot % Nitration Sulfation	Abs/cm Abs/.1mm	*ASTM D7844 *ASTM D7624 *ASTM D7415	>3 >20 >30	8.3 18.9	9.4 22.4	



OIL ANALYSIS REPORT



SCHMIDT TRANSPORTATION - 605449 108 E Bay Road Plattsmouth, NE US 68048 Contact: NICK DOTY doty@liquidtrucking.com T: (402)949-9398 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F:

Diagnostician : Wes Davis

history1

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

history

NEG

NEG

11.6

current

curren

history2

history

Certificate L2367

Unique Number

: 10608605

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Test Package : FLEET (Additional Tests: FuelDilution, PercentFuel)