

PROBLEM SUMMARY

Sample Rating Trend




Thompson Falls THF01 Governor

Case Drain Governor System

LUBRICATION ENG 6802 MULTEC IND OIL 46 (40 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status			ABNORMAL	NORMAL	NORMAL				
Particles >4µm	ASTM D7647	>2500	<u> </u>	387	287				
Particles >6µm	ASTM D7647	>640	△ 648	78	75				
Oil Cleanliness	ISO 4406 (c)	>18/16/13	<u>^</u> 20/17/11	16/13/10	15/13/10				

Customer Id: PPLBUT Sample No.: WC0757772 Lab Number: 05929555 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.

HISTORICAL DIAGNOSIS

12 Oct 2022 Diag: Angela Borella

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The amount and size of particulates present in the system is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



12 Apr 2022 Diag: Jonathan Hester

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The amount and size of particulates present in the system is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



20 Oct 2021 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend


ISO

Thompson Falls Machine Id THF01 Governor

Component

Case Drain Governor System

LUBRICATION ENG 6802 MULTEC IND OIL 46 (40 GAL)



DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

+0 (+0 GAL)		Nov2004	Feb2016 Nov2018	Jul2020 Apr2022	Aug2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0757772	WCI2326099	WCI2326202
Sample Date		Client Info		10 Aug 2023	12 Oct 2022	12 Apr 2022
Machine Age	yrs	Client Info		22	21	21
Oil Age	yrs	Client Info		16	15	15
Oil Changed		Client Info		Filtered	Not Changd	Not Changd
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	1	2	1
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>10	0	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		0	<1	0
Aluminum	ppm	ASTM D5185m	>3	0	<1	<1
Lead	ppm	ASTM D5185m	>75	0	<1	0
Copper	ppm	ASTM D5185m	>15	<1	<1	<1
Tin	ppm	ASTM D5185m	>55	0	0	0
Antimony	ppm	ASTM D5185m	>5			
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	<1
Barium	ppm	ASTM D5185m		0	1	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m		<1	1	0
Calcium	ppm	ASTM D5185m		112	121	118
Phosphorus	ppm	ASTM D5185m		324	319	347
Zinc	ppm	ASTM D5185m		181	201	190
Sulfur	ppm	ASTM D5185m		1025	1077	817
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>8	0	0	<1
Sodium	ppm	ASTM D5185m		5	3	4
Potassium	ppm	ASTM D5185m	>20	0	1	0
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>2500	^ 7087	387	287
Particles >6µm		ASTM D7647	>640	<u></u> 648	78	75
Particles >14µm		ASTM D7647	>80	13	8	10
Particles >21µm		ASTM D7647	>20	4	3	4
Particles >38µm		ASTM D7647	>4	0	0	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>18/16/13	<u>^</u> 20/17/11	16/13/10	15/13/10
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.196	0.18	0.133



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

: 05929555 : 10609502

: WC0757772 Received

Diagnosed Diagnostician

: Angela Borella Test Package : IND 2 (Additional Tests: PrtCount)

: 21 Aug 2023

: 22 Aug 2023

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

NORTHWESTERN ENERGY

6700 RAINBOW DAM RD GREAT FALLS, MT US 59404

Contact: BRIAN WARD brian.ward@northwestern.com

Contact/Location: BRIAN WARD - PPLBUT

T:

F: (406)533-3401