



PROBLEM SUMMARY

CS-46 [PM12-2564901] QUINCY UTY306871 - BOOTH RANCES LLC 2

Compressor

Component





RECOMMENDATION

We advise that you check for a possible overheat condition. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE					
Acid Number (AN)	mg KOH/g	ASTM D8045	0.463	31.39					
Visc @ 40°C	cSt	ASTM D445	47.9	184					

Customer Id: UCCISSAC Sample No.: UCH05933756 Lab Number: 05933756 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	Oil and filter change at the time of sampling has been noted.			
Change Filter			?	Oil and filter change at the time of sampling has been noted.			
Resample			?	We recommend an early resample to monitor this condition.			
Check For Overheating			?	We advise that you check for a possible overheat condition.			


HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

CS-46 [PM12-2564901] QUINCY UTY306871 - BOOTH RANCES LLC 2

Compressor





DIAGNOSIS

Recommendation

We advise that you check for a possible overheat condition. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The oil viscosity is higher than normal. The AN level is above the recommended limit.

				Aug2023		
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UCH05933756		
Sample Date		Client Info		10 Aug 2023		-
Machine Age	hrs	Client Info		9302		_
Oil Age	hrs	Client Info		0		_
Oil Changed	0	Client Info		Changed		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	43		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m		0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	0		
Lead		ASTM D5185m	>25	0		
	ppm			4		
Copper	ppm	ASTM D5185m		_		
Tin	ppm	ASTM D5185m	>15	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	1.5	<1		
Barium	ppm	ASTM D5185m	0	<1		
Molybdenum	ppm	ASTM D5185m	0	0		
Manganese	ppm	ASTM D5185m	0.3	0		
Magnesium	ppm	ASTM D5185m	0	1		
Calcium	ppm	ASTM D5185m	0	4		
Phosphorus	ppm	ASTM D5185m	406	12		
Zinc	ppm	ASTM D5185m	0	29		
Sulfur	ppm	ASTM D5185m	1283	18		
CONTAMINANTS	S	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	<1		
Sodium	ppm	ASTM D5185m		8		
Potassium	ppm	ASTM D5185m	>20	<1		
FLUID DEGRAD	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.463	31.39		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	LIGHT		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual	,	NEG		
10:E0:10) Day: 1	oodidi	riodai	0	toot/Location: D	ADDV EDVOVIOU	LICCICCAC



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number

: UCH05933756 : 05933756 Unique Number : 10619027 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 24 Aug 2023 : 28 Aug 2023 Diagnosed

Diagnostician : Doug Bogart

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

CISCO AIR SYSTEMS

214 27TH ST SACRAMENTO, CA US 95816

Contact: BARRY FRKOVICH barryfrkovich@ciscoair.com

T: (916)444-2525

F: x: