



### **PROBLEM SUMMARY**


# CF6201 (S/N 00881-003-1-01-01)

Gearbox Fluid MOBIL GLYGOYLE 100 (--- GAL)

### COMPONENT CONDITION SUMMARY







### RECOMMENDATION

We advise that you check for the source of water entry. We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

### PROBLEMATIC TEST RESULTS

THODELWATIO	LOTIN	100110				
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
Water	%	ASTM D6304	>0.2	<b>A</b> 0.373	▲ 0.642	<b>0.467</b>
ppm Water	ppm	ASTM D6304	>2000	<b>A</b> 3730	<b>6</b> 420	<b>4</b> 670
Particles >4µm		ASTM D7647	>20000	🔺 168211	▲ 184612	▲ 104408
Particles >6µm		ASTM D7647	>5000	<u> </u>	▲ 57592	<b>à</b> 38492
Particles >14µm		ASTM D7647	>640	🔺 2153	<b>4</b> 935	<b>2</b> 544
Particles >21µm		ASTM D7647	>160	<b>6</b> 542	<b>1</b> 377	<b>4</b> 916
Oil Cleanliness		ISO 4406 (c)	>21/19/16	<u> </u>	<b>a</b> 25/23/19	<b>4</b> /22/19

Customer Id: FLIFAI Sample No.: USP234733 Lab Number: 05934886 Test Package: IND 2



To manage this report scan the QR code

*To discuss the diagnosis or test data:* Doug Bogart +1 (800)237-1369 x4016 <u>dougb@wearcheckusa.com</u>

*To change component or sample information:* Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component if applicable.		
Check Water Access			?	We advise that you check for the source of water entry.		

### HISTORICAL DIAGNOSIS



### 06 Aug 2023 Diag: Jonathan Hester

We advise that you check for the source of water entry. We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. There is a moderate concentration of water present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



view report

### 22 Jun 2023 Diag: Doug Bogart



We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. There is a light concentration of water present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

#### 21 May 2023 Diag: Doug Bogart





#### 21 May 2023 Diag: Doug Bogart

We advise that you check for the source of water entry. Resample at the next service interval to monitor.All component wear rates are normal. There is a light concentration of water present in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.







### **OIL ANALYSIS REPORT**

### Sample Rating Trend

WATER

#### Machine Id CF6201 (S/N 00881-003-1-01-01) Component

Gearbox Fluid MOBIL GLYGOYLE 100 (--- GAL)

### DIAGNOSIS

### Recommendation

We advise that you check for the source of water entry. We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

### Wear

All component wear rates are normal.

### Contamination

There is a high amount of particulates present in the oil. There is a moderate concentration of water present in the oil.


### Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


	ATION		1			
SAMPLE INFORM	<b>MATION</b>	method	limit/base	current	history1	history2
Sample Number		Client Info		USP234733	USP246079	USP246084
Sample Date		Client Info		26 Aug 2023	06 Aug 2023	22 Jun 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	74	3	26
Chromium	ppm	ASTM D5185m	>15	1	0	<1
Nickel	ppm	ASTM D5185m	>15	<1	1	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	0	0	0
Lead	ppm	ASTM D5185m	>100	<1	0	0
Copper	ppm	ASTM D5185m	>200	11	0	0
Tin	ppm	ASTM D5185m	>25	2	<1	<1
Vanadium	ppm	ASTM D5185m		<1	0	<1
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		<1	0	0
Barium	ppm	ASTM D5185m		<1	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		1	<1	<1
Magnesium	ppm	ASTM D5185m		<1	4	0
Calcium	ppm	ASTM D5185m		2	0	0
Phosphorus	ppm	ASTM D5185m		547	286	574
Zinc	ppm	ASTM D5185m		2	0	0
Sulfur	ppm	ASTM D5185m		853	461	778
CONTAMINANTS	6	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	1	0	4
Sodium	ppm	ASTM D5185m		4	0	0
Potassium	ppm	ASTM D5185m	>20	2	5	2
Water	%	ASTM D6304	>0.2	<b>6</b> 0.373	▲ 0.642	▲ 0.467
ppm Water	ppm	ASTM D6304	>2000	<b>A</b> 3730	6420	4670
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	🔺 168211	▲ 184612	104408
Particles >6µm		ASTM D7647	>5000	<u> </u>	▲ 57592	▲ 38492
Particles >14µm		ASTM D7647	>640	<u> </u>	<b>4</b> 935	🔺 2544
Particles >21µm		ASTM D7647	>160	<u> </u>	<b>1</b> 377	<b>4</b> 916
Particles >38µm		ASTM D7647	>40	26	<b>~</b> 75	<b>2</b> 58
Particles >71µm		ASTM D7647	>10	2	4	<b>6</b> 8
Oil Cleanliness		ISO 4406 (c)	>21/19/16	<b>4</b> 25/23/18	▲ 25/23/19	▲ 24/22/19
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.052	0.052	0.09



## **OIL ANALYSIS REPORT**







0.5

(<sup>B</sup>/HOX

Ê 0.30

đ 0.2

0.10


:01 (40°C) 101 (40°C)

100 - B


95

90


8



Color



Bottom



Report Id: FLIFAI [WUSCAR] 05934886 (Generated: 08/29/2023 19:22:26) Rev: 1

Contact/Location: JASON GOEDKEN - FLIFAI