

UTL-M0046

NOT GIVEN (--- GAL)

COOLANT REPORT







DIAGNOSIS

Component Coolant

Recommendation

We recommend drain system, and refill with 50/50 antifreeze water mixture.

Contaminants

There is no indication of any contamination in the coolant.


Coolant Condition

The glycol level is higher than acceptable. The nitrite level is acceptable. The pH level of this fluid is within the acceptable limits.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0789418		
Sample Date		Client Info		28 Aug 2023		
Machine Age	hrs	Client Info		749		
Oil Age	hrs	Client Info		749		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
PHYSICAL TEST R	ESULTS	method	limit/base	current	history1	history2
Specific Gravity		*ASTM D1298		1.093		
рН	Scale 0-14	ASTM D1287		8.46		
Nitrites	ppm	AP-053:2009		3004		
Reserve Alkalinity	Scale 0-20	*ASTM D1121				
Percentage Glycol	%	ASTM D3321		73.3		
Freezing Point	°F	ASTM D3321		-64		
Total Dissolved Solids				850.5		
Carboxylate				n/a		
VISUAL		method	limit/base	current	history1	history2
Coolant Color		*Visual		Orange		
Coolant Appearance		*Visual	Clear	normal		
Color				3,85/10	no image	no image
Bottom					no image	no image



COOLANT REPORT





Certificate L2367

Laboratory Sample No. Lab Number

: WC0789418 : 05938495 Unique Number : 10629107

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 30 Aug 2023 Diagnosed

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

: 04 Sep 2023 Diagnostician : Doug Bogart

Test Package : COOL- (Additional Tests: COOL)

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

To discuss this sample report, contact Customer Service at 1-800-237-1369.

ALTERNATIVE POWER 1000 NORTHGATE CT

MORRISVILLE, NC US 27560 Contact: ROBERT MCARTHUR

rmcarthur@bittingelectric.com T: (919)467-9417