


OIL ANALYSIS REPORT

Enviromental

Truck Fill Bin Hydraulic Unit (S/N EN215T10H)

Hydraulic System

DEXRON III (--- GAL)





DIAGNOSIS

Recommendation

Little or no information is provided as to the component and lubricant being tested.

Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm.

NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

2020 0x2020 Feb2021 Ju02021 0x2021 Aug2022 0x2022 Jun2023						
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0783011	WC0734574	WC0782973
Sample Date		Client Info		25 Sep 2023	22 Aug 2023	24 Jul 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	12	9	13
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	0	0	0
Lead	ppm	ASTM D5185m	>20	<1	0	<1
Copper	ppm	ASTM D5185m	>20	6	5	7
Tin	ppm	ASTM D5185m	>20	<1	<1	<1
Vanadium	ppm	ASTM D5185m		0	<1	0
Cadmium	ppm	ASTM D5185m		<1	<1	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		116	104	104
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	0	<1
Magnesium	ppm	ASTM D5185m		0	0	1
Calcium	ppm	ASTM D5185m		107	104	112
Phosphorus	ppm	ASTM D5185m		245	234	237
Zinc	ppm	ASTM D5185m		19	17	30
Sulfur	ppm	ASTM D5185m		989	1070	1081
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	2	2	2
Sodium	ppm	ASTM D5185m		4	4	5
Potassium	ppm	ASTM D5185m	>20	2	0	2
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	3493	4082	1731
Particles >6µm		ASTM D7647	>640	270	593	△ 943
Particles >14μm		ASTM D7647	>80	9	34	<u> </u>
Particles >21µm		ASTM D7647	>20	2	9	<u></u> ▲ 54
Particles >38μm		ASTM D7647	>4	0	0	<u>^</u> 8
Particles >71µm		ASTM D7647	>3	0	0	1
Oil Cleanliness		ISO 4406 (c)	>19/16/13	19/15/10	19/16/12	<u>▲</u> 18/17/15
FLUID DEGRADA	NOITA	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.75	0.77	0.75



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number **Unique Number** Test Package

: WC0783011 : 05964166 : 10670717 : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 28 Sep 2023 Received : 29 Sep 2023 Diagnosed : Wes Davis Diagnostician

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

J.M. Huber Corporation

PO BOX 38 CRYSTAL HILL, VA US 24539

Contact: Ted Hudson ted.hudson@huber.com T: (434)476-6628

F: (434)476-8133

Contact/Location: Ted Hudson - JMHCRY