

PROBLEM SUMMARY

Sample Rating Trend

ISO


IRIG [6076655]

IRIG-BLR-HPU-0901 IRIG-BLR-HPU-0901 HPU-GENERATOR MODULE

Component **Pump** Fluid

MOBIL DTE 10 EXCEL 32 (140 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATIC TES	T RESULTS				
Sample Status			ABNORMAL	ABNORMAL	NORMAL
Particles >4μm	ASTM D7647 >	>2500	<u> </u>	<u>▲</u> 8236	653
Particles >6µm	ASTM D7647 >	>640	1653	<u></u> ▲ 644	113
Oil Cleanliness	ISO 4406 (c) >	>18/16/14	<u>^</u> 20/18/13	<u>^</u> 20/17/11	17/14/11

Customer Id: BPEMPU Sample No.: HLC0002806 Lab Number: 05964175 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.

HISTORICAL DIAGNOSIS

08 Sep 2023 Diag: Doug Bogart





No corrective action is recommended at this time. The filtration at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



29 Jul 2023 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



30 Jun 2023 Diag: Doug Bogart

NORMAL



Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend

ISO

A

IRIG [6076655]

IRIG-BLR-HPU-0901 IRIG-BLR-HPU-0901 HPU-GENERATOR MODULE

Component

Pump

MOBIL DTE 10 EXCEL 32 (140 GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORMATION	method	limit/base	current	his
GENERATOR MODULE	2016 Apr2019	Jan R020 Jul2020 Nors2021	Maylozz Novčozz Nagloz	3
SIS REPORT				


Sample Number		Client Info		HLC0002806	HLC0002825	HLC0002706
Sample Date		Client Info		19 Sep 2023	08 Sep 2023	29 Jul 2023
Machine Age	hrs	Client Info		786	786	771
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	Filtered	N/A
Sample Status				ABNORMAL	ABNORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>90	1	2	2
Chromium	ppm	ASTM D5185m	>5	0	0	0
Nickel	ppm	ASTM D5185m	>5	0	0	<1
Titanium	ppm	ASTM D5185m	>3	0	<1	0
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>7	0	<1	0
Lead	ppm	ASTM D5185m	>12	0	0	0
Copper	ppm	ASTM D5185m	>30	8	8	8
Tin	ppm	ASTM D5185m	>9	0	0	0
Vanadium	ppm	ASTM D5185m		0	<1	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	0
Magnesium	ppm	ASTM D5185m		0	0	0
Calcium	ppm	ASTM D5185m	120	102	113	97
Phosphorus	ppm	ASTM D5185m	475	447	467	415
Zinc	ppm	ASTM D5185m		56	33	61
Sulfur	ppm	ASTM D5185m	1275	1485	1798	1568
CONTAMINANTS	}	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>60	<1	<1	1
Sodium	ppm	ASTM D5185m		2	3	0
Potassium	ppm	ASTM D5185m	>20	2	<1	1
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>2500	105	<u>▲</u> 8236	653
Particles >6μm		ASTM D7647	>640	<u> </u>	<u></u> ▲ 644	113
Particles >14µm		ASTM D7647	>160	70	11	19
Particles >21µm		ASTM D7647	>40	13	2	8
Particles >38µm		ASTM D7647	>10	0	0	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>18/16/14	<u>^</u> 20/18/13	<u>^</u> 20/17/11	17/14/11
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.06	0.141	0.052




OIL ANALYSIS REPORT



15k -	6μm 14μm				
0k -		٨		1	
5k - Abnor	1	1			1







VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
	150	and the section of	11 11 11		Internal	In late on O

I LOID I NOI LI	TILO	memou	IIIIII/Dase	Current	HISTOLAL	HISTOLA
Visc @ 40°C	cSt	ASTM D445	32	32.3	32.5	32.2

|--|


Bottom






GRAPHS

Color









Laboratory Sample No. Lab Number Unique Number

: 05964175 : 10670726

£ 30

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : HLC0002806 Received Diagnosed

: 28 Sep 2023 : 01 Oct 2023

May14/23

₹ 0.10 0.00 G

Diagnostician : Don Baldridge

Test Package : IND 2 (Additional Tests: PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

HILCORP EXPLORATION ALASKA - MILNE POINT

1000 MILNE POINT RD PRUDOE BAY, AK US 99734

Contact: Evan Reilly evan.reilly@hilcorp.com T: (907)670-3231

F: x: