

PROBLEM SUMMARY

Sample Rating Trend

ISO

IRIG [6076666]

IRIG-PRM-HPU-0301 IRIG-PRM-HPU-0301 HPU MUD MODULE


Hydraulic System

MOBIL DTE 10 EXCEL 32 (--- GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS								
Sample Status			ABNORMAL	ABNORMAL	NORMAL			
Particles >4µm	ASTM D7647	>2500	12862	▲ 8337	562			
Particles >6μm	ASTM D7647	>640	2669	504	82			
Oil Cleanliness	ISO 4406 (c)	>18/16/14	21/19/14	2 0/16/10	16/14/11			

Customer Id: BPEMPU Sample No.: HLC0002790 Lab Number: 05964180 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.
Resample			?	We recommend an early resample to monitor this condition.
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

HISTORICAL DIAGNOSIS

08 Sep 2023 Diag: Wes Davis

ISO



We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



29 Jul 2023 Diag: Jonathan Hester

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



30 Jun 2023 Diag: Doug Bogart

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

SAMPLE INFORMATION

Sample Number

Sample Rating Trend

method

Client Info

ISO

HLC0002716

IRIG [6076666]

IRIG-PRM-HPU-0301 IRIG-PRM-HPU-0301 HPU MUD MODULE

Componen

Hydraulic System

MOBIL DTE 10 EXCEL 32 (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear


All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



current

HLC0002790

history1

HLC0002828


limit/base


Sample Date		Client Info		17 Sep 2023	08 Sep 2023	29 Jul 2023
Machine Age	hrs	Client Info		1018	1018	1002
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	Filtered	N/A
Sample Status				ABNORMAL	ABNORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	1	2	1
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	<1
Titanium	ppm	ASTM D5185m		0	<1	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	0	<1	0
Lead	ppm	ASTM D5185m	>20	0	0	0
Copper	ppm	ASTM D5185m	>20	6	7	6
Tin	ppm	ASTM D5185m	>20	0	0	0
Vanadium	ppm	ASTM D5185m		0	<1	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	0
Magnesium	ppm	ASTM D5185m		0	0	0
Calcium	ppm	ASTM D5185m	120	104	114	100
Phosphorus	ppm	ASTM D5185m	475	450	471	417
Zinc	ppm	ASTM D5185m		37	15	47
Sulfur	ppm	ASTM D5185m	1275	1396	1704	1544
CONTAMINANTS)	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1	<1	<1
Sodium	ppm	ASTM D5185m		3	3	0
Potassium	ppm	ASTM D5185m	>20	2	1	1
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>2500	12862	▲ 8337	562
Particles >6µm		ASTM D7647	>640	<u>^</u> 2669	504	82
Particles >14µm		ASTM D7647	>160	98	6	11
Particles >21µm		ASTM D7647	>40	17	1	4
Particles >38µm		ASTM D7647	>10	0	0	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>18/16/14	<u>^</u> 21/19/14	2 0/16/10	16/14/11
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.233	0.087	0.125




Acid Number

OIL ANALYSIS REPORT







VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2

SAMPLE IMAGES	method	limit/base	current	historv1	historv2

31.6

ASTM D445 32

Color

Visc @ 40°C




cSt



32.6

32.73





Certificate L2367

Report Id: BPEMPU [WUSCAR] 05964180 (Generated: 09/29/2023 15:31:00) Rev: 1

Laboratory Sample No.

Test Package : IND 2

Lab Number **Unique Number**

: HLC0002790 : 05964180 : 10670731

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 29 Sep 2023 Diagnostician : Wes Davis

: 28 Sep 2023

HILCORP EXPLORATION ALASKA - MILNE POINT

1000 MILNE POINT RD PRUDOE BAY, AK US 99734 Contact: Evan Reilly

evan.reilly@hilcorp.com T: (907)670-3231

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: Evan Reilly - BPEMPU

F: x: