

COOLANT REPORT

Sample Rating Trend

OFF SPEC

1767 WILMAT WRITTEN ON BOTTLE

NAPA COOLANT (--- GAL)

DIAGNOSIS

Recommendation

We recommend drain system, and refill with 50/50 antifreeze water mixture. We advise that you replenish the supplemental coolant additives (SCAs) and add per manufacturer's specifications.

Contaminants

There is no indication of any contamination in the coolant.

Coolant Condition


The glycol level is higher than acceptable. The nitrite level is acceptable. The pH level of this fluid is within the acceptable limits.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0757415		
Sample Date		Client Info		22 Sep 2023		
Machine Age	hrs	Client Info		1825		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				ABNORMAL		
PHYSICAL TEST R	ESULTS	method	limit/base	current	history1	history2
Specific Gravity		*ASTM D1298		1.092		
рН	Scale 0-14	ASTM D1287		9.38		
Nitrites	ppm	AP-053:2009		1124		
Reserve Alkalinity	Scale 0-20	*ASTM D1121				
Percentage Glycol	%	ASTM D3321		A 72.4		
Freezing Point	°F	ASTM D3321		-65		
Total Dissolved Solids				355.0		
Carboxylate				n/a		
VISUAL		method	limit/base	current	history1	history2
Coolant Color		*Visual		Orange		
Coolant Appearance		*Visual	Clear	normal		
Color					no image	no image
Bottom					no image	no image





COOLANT REPORT



Contact/Location: BILL HOOD - HSSBEA