

PROBLEM SUMMARY

Sample Rating Trend

1003 Audios Audios 1-401 1-401 0 401 0 402 0

ISO




FRICK TYSCLA 14 (S/N TDSH23352861EZ)

Refrigeration Compressor

USPI ALT-68 SC (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status		Į.	ABNORMAL	ABNORMAL	ABNORMAL			
Particles >4µm	ASTM D7647 >	10000	<u>242486</u>	<u>124715</u>	<u>23278</u>			
Particles >6µm	ASTM D7647 >	2500	99615	<u>▲</u> 37235	<u></u> 5078			
Particles >14μm	ASTM D7647 >	320	2381	<u></u> 502	261			
Particles >21μm	ASTM D7647 >	80	305	25	57			
Oil Cleanliness	ISO 4406 (c) >2	20/18/15	25/24/18	<u>4</u> 24/22/16	<u>22/20/15</u>			

Customer Id: TYSCLA Sample No.: USP0002974 Lab Number: 05995651 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.

HISTORICAL DIAGNOSIS

05 Jan 2023 Diag: Doug Bogart





We recommend you service the filters on this component. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



06 Aug 2020 Diag: Doug Bogart

ISO



Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



20 Jan 2020 Diag: Doug Bogart

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The amount and size of particulates present in the system is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



FRICK TYSCLA 14 (S/N TDSH23352861EZ)

Refrigeration Compressor

USPI ALT-68 SC (--- GAL)





DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

Wear

An increase in the iron level is noted.

Contamination

There is a high amount of particulates present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

		n2007 Apr20		Jan2013 Sep2014 Sep2017 S	Sep 2019	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		USP0002974	USP244427	USP214244
Sample Date		Client Info		31 Oct 2023	05 Jan 2023	06 Aug 2020
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>8	10	3	<1
Chromium	ppm	ASTM D5185m	>2	0	0	0
Nickel	ppm	ASTM D5185m		<1	1	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>3	0	<1	0
Lead	ppm	ASTM D5185m	>2	0	0	0
Copper	ppm	ASTM D5185m	>8	0	<1	0
Tin	ppm	ASTM D5185m	>4	0	0	0
Antimony	ppm	ASTM D5185m				0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m		<1	1	0
Calcium	ppm	ASTM D5185m		<1	0	0
Phosphorus	ppm	ASTM D5185m		<1	0	0
Zinc	ppm	ASTM D5185m		0	0	0
Sulfur	ppm	ASTM D5185m	50	18	0	22
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	2	2	3
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	<1	<1	0
Water	%	ASTM D6304	>0.01	0.002	0.003	0.003
ppm Water	ppm	ASTM D6304	>100	21.1	30.9	33.0
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	242486	<u>124715</u>	△ 23278
Particles >6µm		ASTM D7647	>2500	<u>\$\text{\$\text{\$}}\$ 99615</u>	▲ 37235	▲ 5078
Particles >14µm		ASTM D7647	>320	<u>2381</u>	▲ 502	261
Particles >21µm		ASTM D7647	>80	△ 305	25	57
Particles >38µm		ASTM D7647	>20	2	1	1
Particles >71µm		ASTM D7647	>4	0	0	0
Oil Cleanliness		ISO 4406 (c)	>20/18/15	25/24/18	<u>4</u> 24/22/16	<u>△</u> 22/20/15
FLUID DEGRADA	TION	method	limit/base	current	history1	history2



OIL ANALYSIS REPORT





Certificate L2367

Lab Number **Unique Number**

: 05995651

: 10724011 Test Package : IND 2

: 03 Nov 2023 Diagnosed

Diagnostician : Doug Bogart CLARKSVILLE, AR US

Contact: BRENT SMITH

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: F: