

# **PROBLEM SUMMARY**

## Sample Rating Trend

WEAR



# KENWORTH 3904


Component

Front Differentia

**Front Differential** 

NOT GIVEN (--- QTS)

## COMPONENT CONDITION SUMMARY



### RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL				
Iron	ppm	ASTM D5185m	>500	<u> </u>				

Customer Id: LTILYN
Sample No.: WCMFB85531
Lab Number: 05996020
Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:
Don Baldridge +1
don.b505@comcast.net

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS								
Action	Status	Date	Done By	Description				
Information Required			?	Please specify the brand, type, and viscosity of the oil on your next sample.				
HISTORICAL DIAGN	IOSIS							



# **OIL ANALYSIS REPORT**

Sample Rating Trend




# **KENWORTH 3904**

Component

**Front Differential** 

NOT GIVEN (--- QTS)



## **DIAGNOSIS**

#### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.

## Wear

Gear wear is indicated. All other component wear rates are normal.

#### Contamination

There is no indication of any contamination in the


### **Fluid Condition**

The condition of the oil is acceptable for the time in service.

		<u>,                                    </u>		Oct2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WCMFB85531		
Sample Date		Client Info		31 Oct 2023		
Machine Age	mls	Client Info		0		
Oil Age	mls	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	<b>▲</b> 622		
Chromium	ppm	ASTM D5185m	>10	5		
Nickel	ppm	ASTM D5185m	>10	5		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	4		
Lead	ppm	ASTM D5185m	>25	2		
Copper	ppm	ASTM D5185m		30		
Tin	ppm	ASTM D5185m	>100	2		
Vanadium	ppm	ASTM D5185m	>10	0		
Cadmium		ASTM D5185m		<1		
	ppm					
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		198		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		2		
Manganese	ppm	ASTM D5185m		7		
Magnesium	ppm	ASTM D5185m		4		
Calcium	ppm	ASTM D5185m		15		
Phosphorus	ppm	ASTM D5185m		1295		
Zinc	ppm	ASTM D5185m		7		
Sulfur	ppm	ASTM D5185m		25224		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	35		
Sodium	ppm	ASTM D5185m		2		
Potassium	ppm	ASTM D5185m	>20	2		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>.2	NEG		
Free Water	scalar	*Visual		NEG		
FLUID PROPERT	IES	method	limit/base	current	history1	history2



## **OIL ANALYSIS REPORT**







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10724380

: WCMFB85531 : 05996020 Test Package : FLEET

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 01 Nov 2023 : 03 Nov 2023 Diagnosed Diagnostician : Don Baldridge

LTI/MILKY WAY - MOUNT VERNON

3814 OLD HWY 99 S RD MOUNT VERNON, WA US 98273

Contact: JOHN VAN WINGERDEN

jvw@lynden.com T: (360)354-2101 F: (360)354-3571

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)