

# **PROBLEM SUMMARY**

Sample Rating Trend

ISO




MP-105

B52525 - PUMP VACUUM BUSCH RA0630 HAM LINE 1 (TOP) (S/N U093504072)

Top Pump

PETRO CANADA PURITY FG SYNTHETIC 100 (--- GAL)

# **COMPONENT CONDITION SUMMARY**



# RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status			ATTENTION	NORMAL	NORMAL				
Particles >4µm	ASTM D7647	>10000	<u> </u>	3477	820				
Particles >6µm	ASTM D7647	>2500	<b>▲</b> 3798	458	202				
Oil Cleanliness	ISO 4406 (c)	>20/18/15	<b>1</b> 21/19/13	19/16/10	17/15/11				

Customer Id: HORAUS Sample No.: WC0856015 Lab Number: 05996667 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

# **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

# HISTORICAL DIAGNOSIS

# 12 Sep 2023 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



#### 24 May 2023 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



### 20 Mar 2023 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





# **OIL ANALYSIS REPORT**

Sample Rating Trend



MP-105

B52525 - PUMP VACUUM BUSCH RA0630 HAM LINE 1 (TOP) (S/N U093504072)

Top Pump

PETRO CANADA PURITY FG SYNTHETIC 100 (--- GAL)

# **DIAGNOSIS**

#### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

All component wear rates are normal.

# Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.


#### **Fluid Condition**


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


		w2016 Feb201	7 Dec2017 Mar2019 Dec20	119 Nov2020 Sep2021 Apr2022 J	an 2023 Oct20	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0856015	WC0838656	WC0799673
Sample Date		Client Info		28 Oct 2023	12 Sep 2023	24 May 2023
Machine Age	yrs	Client Info		0	0	0
Oil Age	yrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ATTENTION	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>90	3	4	6
Chromium	ppm	ASTM D5185m	>5	<1	0	0
Nickel	ppm	ASTM D5185m	>5	0	0	0
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>7	<1	0	2
Lead	ppm	ASTM D5185m	>12	0	0	0
Copper	ppm	ASTM D5185m	>30	<1	0	0
Tin	ppm	ASTM D5185m	>9	0	<1	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m		<1	2	0
Calcium	ppm	ASTM D5185m		0	0	0
Phosphorus	ppm	ASTM D5185m		322	357	400
Zinc	ppm	ASTM D5185m		0	0	0
Sulfur	ppm	ASTM D5185m		956	1106	1223
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>60	3	4	2
Sodium	ppm	ASTM D5185m		0	<1	<1
Potassium	ppm	ASTM D5185m	>20	1	<1	0
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	<u> </u>	3477	820
Particles >6µm		ASTM D7647	>2500	<u> </u>	458	202
Particles >14µm		ASTM D7647	>320	65	10	19
Particles >21µm		ASTM D7647	>80	10	2	4
Particles >38µm		ASTM D7647	>20	0	1	0
Particles >71µm		ASTM D7647	>4	0	1	0
Oil Cleanliness		ISO 4406 (c)	>20/18/15	<u>^</u> 21/19/13	19/16/10	17/15/11
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.5	0.06	0.079	0.10



# **OIL ANALYSIS REPORT**







00.00 PG

Oct28/23

: 02 Nov 2023



cSt (

100

90



Certificate L2367

Laboratory

Sample No. Lab Number **Unique Number** 

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0856015 : 05996667 : 10725027

Received

Diagnosed : 04 Nov 2023 : Don Baldridge Diagnostician

Test Package : IND 2 ( Additional Tests: PrtCount ) To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**HORMEL FOODS - AUSTIN** 

1101 NORTH MAIN ST AUSTIN, MN US 55912

Contact: RYAN LOWE rslowe@hormel.com T: (507)437-5674

Contact/Location: RYAN LOWE - HORAUS

F: (507)437-9805

20 8