

PROBLEM SUMMARY

Sample Rating Trend


ISO

T-3 NORTH VAC MILL (SOUTH PLANT)

Agitator Gearbox

JAX MAGNA-PLATE 220 FG (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status			ATTENTION						
Particles >4µm	ASTM D7647	>20000	28791						
Oil Cleanliness	ISO 4406 (c)	>21/19/16	22/19/13						

Customer Id: TYSSAI Sample No.: USP0003054 Lab Number: 05996717 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend

ISO

Machine Id

T-3 NORTH VAC MILL (SOUTH PLANT)

Component

Agitator Gearbox

JAX MAGNA-PLATE 220 FG (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 6 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Nov2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		USP0003054		
Sample Date		Client Info		01 Nov 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ATTENTION		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>150	22		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	<1		
Lead	ppm	ASTM D5185m	>100	0		
Copper	ppm	ASTM D5185m	>50	<1		
Tin	ppm	ASTM D5185m	>10	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		1		
Barium	ppm	ASTM D5185m		<1		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		<1		
Calcium	ppm	ASTM D5185m		1		
Phosphorus	ppm	ASTM D5185m		391		
Zinc	ppm	ASTM D5185m		6		
Sulfur	ppm	ASTM D5185m		9825		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	2		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	3		
Water	%	ASTM D6304	>0.1	0.011		
ppm Water	ppm	ASTM D6304	>1000	110.5		
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	<u>28791</u>		
Particles >6µm		ASTM D7647	>5000	4170		
Particles >14µm		ASTM D7647	>640	63		
Particles >21µm		ASTM D7647	>160	11		
Particles >38µm		ASTM D7647	>40	1		
Particles >71µm		ASTM D7647	>10	0		
Oil Cleanliness		ISO 4406 (c)	>21/19/16	22/19/13		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (ANI)	ma 1/011/a	ACTM DODAE		0.47		

0.47

Acid Number (AN)

mg KOH/g ASTM D8045



OIL ANALYSIS REPORT





Certificate L2367

Laboratory Sample No. Lab Number Unique Number

Test Package

: USP0003054 : 05996717

Received : 10725077

: 02 Nov 2023 Diagnosed : 06 Nov 2023 Diagnostician : Doug Bogart

TYSON HILLSHIRE - SAINT JOSEPH

5807 MITCHELL AVE SAINT JOSEPH, MO US 64507

Contact:

T: F:

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: IND 2

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)