

PROBLEM SUMMARY

Sample Rating Trend

WEAR




HYDR Machine Id [HYDR] PUMP, #2 HYD (BFW) BOILER FEED WATER, SOUTH Component

Pump Fluid

ROYAL PURPLE SYNFILM GT 32 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status				ABNORMAL						
Lead	ppm	ASTM D5185m	>12	<u>^</u> 20						
Copper	ppm	ASTM D5185m	>30	47						

Customer Id: CALSHR Sample No.: RP0034761 Lab Number: 05998484 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

Area **HYDR** [HYDR] PUMP, #2 HYD (BFW) BOILER FEED WATER, SOUTH

Pump Fluid

ROYAL PURPLE SYNFILM GT 32 (--- GAL)





DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Bearing and/or bushing wear is indicated.

Contamination

There is no indication of any contamination in the


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

)				Oct2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		RP0034761		
Sample Date		Client Info		31 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>90	12		
Chromium	ppm	ASTM D5185m	>5	0		
Nickel	ppm	ASTM D5185m	>5	0		
Titanium	ppm	ASTM D5185m	>3	0		
Silver	ppm	ASTM D5185m	>3	0		
Aluminum	ppm	ASTM D5185m	>7	0		
Lead	ppm	ASTM D5185m	>12	<u>^</u> 20		
Copper	ppm	ASTM D5185m	>30	47		
Tin	ppm	ASTM D5185m	>9	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		3		
Magnesium	ppm	ASTM D5185m		19		
Calcium	ppm	ASTM D5185m		0		
Phosphorus	ppm	ASTM D5185m		55		
Zinc	ppm	ASTM D5185m		7		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>60	8		
Sodium	ppm	ASTM D5185m		4		
Potassium	ppm	ASTM D5185m	>20	0		
Water	%	ASTM D6304	>.1	0.023		
ppm Water	ppm	ASTM D6304	>1000	235.8		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.28		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>.1	NEG		
14 Free Water	scalar	*Visual		NEG	Submitted By:	NICK-FLUHART



OIL ANALYSIS REPORT





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: RP0034761 : 05998484 : 10726844 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 03 Nov 2023 Diagnosed : 07 Nov 2023 Diagnostician : Don Baldridge

CALUMET 3333 MIDWAY AVENUE SHREVEPORT, LA US 71109

Contact: NICHOLAS LESAGE nicholas.lesage@clmt.com

F:

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) T: