

PROBLEM SUMMARY

Sample Rating Trend

DEGRADATION





Machine Id **6113866**


Component **Diesel Engine**

NOT GIVEN (--- GAL)

COMPONENT CONDITION SUMMARY







RECOMMENDATION

We recommend that you drain the oil and perform a filter service on this component if not already done. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL	
Iron	ppm	ASTM D5185m	>100	<u> </u>	
Base Number (BN)	ma KOH/a	ASTM D2896		2.4	

Customer Id: IDEATLGA Sample No.: IL05998575 Lab Number: 05998575 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net


To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	We recommend that you drain the oil and perform a filter service on this component if not already done.		
Change Filter			?	We recommend that you drain the oil and perform a filter service on this component if not already done.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT







Machine Id **6113866** Component

Diesel Engine

NOT GIVEN (--- GAL)

DIAGNOSIS

Recommendation

We recommend that you drain the oil and perform a filter service on this component if not already done. Resample at the next service interval to monitor.

Cylinder, crank, or cam shaft wear is indicated.

Contamination

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components.


▲ Fluid Condition

The BN level is low.

				Oct2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		IL05998575		
Sample Date		Client Info		13 Oct 2023		
Machine Age	mls	Client Info		123031		
Oil Age	mls	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION	V	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
Glycol		WC Method		NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	<u> </u>		
Chromium	ppm	ASTM D5185m		3		
Nickel	ppm	ASTM D5185m	>4	1		
Titanium	ppm	ASTM D5185m	/T	ا <1		
Silver	ppm	ASTM D5185m	>3	0		
Aluminum	ppm	ASTM D5185m		27		
Lead	ppm	ASTM D5185m	>40	0		
Copper	ppm	ASTM D5185m		5		
Tin		ASTM D5185m	>15	<1		
Vanadium	ppm	ASTM D5185m	>10	<1		
Cadmium		ASTM D5185m		0		
Gaumum	ppm	ASTIVI DOTOSIII		U		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		30		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		58		
Manganese	ppm	ASTM D5185m		2		
Magnesium	ppm	ASTM D5185m		736		
Calcium	ppm	ASTM D5185m		2196		
Phosphorus	ppm	ASTM D5185m		1017		
Zinc	ppm	ASTM D5185m		1261		
Sulfur	ppm	ASTM D5185m		2753		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	14		
Sodium	ppm	ASTM D5185m		5		
Potassium	ppm	ASTM D5185m	>20	42		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	1.2		
Nitration	Abs/cm	*ASTM D7624	>20	16.8		
Sulfation	Abs/.1mm	*ASTM D7415		30.5		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	36.7		
Base Number (BN)	mg KOH/g	ASTM D2896		<u>^</u> 2.4		
(2/1)	9					



OIL ANALYSIS REPORT





Certificate L2367

Sample No. Lab Number Unique Number

: IL05998575 : 05998575 : 10726935

Test Package : FLEET

Received : 06 Nov 2023 Diagnosed : 07 Nov 2023

: Don Baldridge Diagnostician

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

4675 BAKERS FERRY ROAD ATLANTA, GA

US 30331 Contact: DAVID JOHNS

davidjohns@idealease.com

T: (404)699-5571 F: (404)699-7420