

PROBLEM SUMMARY

Sample Rating Trend

VISCOSITY

VISCOSITI


PRESS 7 STRETCHER


Component

Hydraulic System

TEXACO RANDO OIL HD 68 (--- GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status				ATTENTION	ATTENTION	ATTENTION				
Particles >4µm		ASTM D7647	>5000	<u> </u>	1185	1898				
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u> </u>	17/15/11	18/16/12				
Visc @ 40°C	cSt	ASTM D445	65.5	<u> </u>	△ 50.4	△ 64.5				

Customer Id: KAIRICVA Sample No.: WC0782202 Lab Number: 06001031 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

24 Jan 2023 Diag: Jonathan Hester

VISCOSITY



No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. Viscosity of sample indicates oil is within ISO 46 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.



06 Apr 2022 Diag: Angela Borella

VISCOSITY



Resample at the next service interval to monitor. All component wear rates are normal. The amount and size of particulates present in the system are acceptable. Viscosity of sample indicates oil is within ISO 68 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



30 Sep 2021 Diag: Jonathan Hester

VISCOSITY




No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. Viscosity of sample indicates oil is within ISO 68 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.





OIL ANALYSIS REPORT

Sample Rating Trend



VISCOSITY

A

PRESS 7 STRETCHER

Component

Hydraulic System

TEXACO RANDO OIL HD 68 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.


▲ Fluid Condition

The oil viscosity is lower than normal. Confirm oil type. The AN level is acceptable for this fluid.

		May2019	Jan2020 Aug2020	Jan2021 Apr2022	Nov2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0782202	WC0555697	WC0573687
Sample Date		Client Info		03 Nov 2023	24 Jan 2023	06 Apr 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ATTENTION	ATTENTION	ATTENTION
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	11	11	<1
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>20	0	0	0
Lead	ppm	ASTM D5185m	>20	0	<1	2
Copper	ppm	ASTM D5185m	>20	7	11	4
Tin	ppm	ASTM D5185m	>20	0	0	<1
Antimony	ppm	ASTM D5185m				
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0.2	0	0	1
Barium	ppm	ASTM D5185m	0	0	1	0
Molybdenum	ppm	ASTM D5185m	0	0	<1	<1
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m	0	24	32	103
Calcium	ppm	ASTM D5185m	49	54	61	85
Phosphorus	ppm	ASTM D5185m	247	356	369	466
Zinc	ppm	ASTM D5185m	323	417	444	548
Sulfur	ppm	ASTM D5185m	4717	867	903	1223
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	0	<1	0
Sodium	ppm	ASTM D5185m		2	0	1
Potassium	ppm	ASTM D5185m	>20	0	1	0
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844		0	0	0
Nitration	Abs/cm	*ASTM D7624		2.1	2.3	2.3
Sulfation	Abs/.1mm	*ASTM D7415		11.2	10.9	11.2
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	7217	1185	1898
Particles >6µm		ASTM D7647	>1300	939	234	401
Particles >14µm		ASTM D7647	>160	72	20	25
Particles >21µm		ASTM D7647	>40	19	5	6
Particles >38µm		ASTM D7647	>10	1	0	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u> </u>	17/15/11	18/16/12



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: 06001031 : 10729391

: WC0782202

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 07 Nov 2023 Received Diagnosed Diagnostician

: 09 Nov 2023 : Don Baldridge

Test Package : IND 2 (Additional Tests: FT-IR)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

KAISER ALUMINUM

1901 REYMET RD NORTH CHESTERFIELD, VA

US 23237

Contact: Yong Quan Yong.Quan@kaiseraluminum.com

T: (804)743-6485