

PROBLEM SUMMARY

Sample Rating Trend


ISO

PALFINGER Tyngsboro 56138

2 Hydraulic System

AW HYDRAULIC OIL ISO 32 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 32. Please confirm.

PROBLEMATIC TEST RESULTS								
Sample Status			SEVERE					
Particles >4µm	ASTM D7647	>5000	9467					
Particles >6µm	ASTM D7647	>1300	7899					
Oil Cleanliness	ISO 4406 (c)	>19/17/14	23/20/12					

Customer Id: PALJACNJ Sample No.: WC0839792 Lab Number: 06006272 Test Package: CONST



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component.		
Resample			?	Resample in 30-45 days to monitor this situation.		
Alert			?	The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 32. Please confirm.		
Information Required			?	The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 32. Please confirm.		
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.		
Check Seals			?	Check seals and/or filters for points of contaminant entry.		

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

PALFINGER Tyngsboro 56138

2 Hydraulic System

AW HYDRAULIC OIL ISO 32 (--- GAL)



DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 32. Please confirm.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.


				Nov2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0839792		
Sample Date		Client Info		01 Nov 2023		
Machine Age	hrs	Client Info		1392		
Oil Age	hrs	Client Info		1392		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	9		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>10	0		
Lead	ppm	ASTM D5185m	>10	<1		
Copper	ppm	ASTM D5185m	>75	<1		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0		
Barium	ppm	ASTM D5185m	5	0		
Molybdenum	ppm	ASTM D5185m	5	0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	25	5		
Calcium	ppm	ASTM D5185m	200	66		
Phosphorus	ppm	ASTM D5185m	300	333		
Zinc	ppm	ASTM D5185m	370	424		
Sulfur	ppm	ASTM D5185m	2500	1031		
CONTAMINANT	S	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	1		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	0		
FLUID CLEANLII	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	9 79467		
Particles >6µm		ASTM D7647	>1300	7899		
Particles >14µm		ASTM D7647	>160	26		
Particles >21µm		ASTM D7647	>40	6		
Particles >38µm		ASTM D7647	>10	0		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	23/20/12		
FLUID DEGRAD	ATION_	method	limit/base	current	history1	history2
Aoid Number (AN)	та КОЦ/а	ACTM DODAE	0.57	0.25		

Acid Number (AN) mg KOH/g ASTM D8045 0.57

0.25



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number Unique Number

: WC0839792 : 06006272 : 10740034 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 13 Nov 2023 : 14 Nov 2023 Diagnosed : Wes Davis Diagnostician

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

PALFINGER - BRANCH 410 632 CEDAR SWAMP RD

JACKSON, NJ US 08527

Contact: DON DRESS d.dress@palfinger.com

T: F: