

FUEL REPORT

Sample Rating Trend

NORMAL



WESTCHESTER CO DIT-RT 2 MOHANSIC GOLF COURSE J110264879

Component

Diesel Fuel
Fluid

NOT GIVEN (--- GAL)


Recommendation


This is a baseline read-out on the submitted sample.

	oupzoro	oop.o.o	DOULDET OUPLOLE	opene	
ATION	method	limit/base	current	history1	history2
	Client Info		WC0834507	WC0699418	WC0612465
	Client Info		29 Sep 2023	29 Sep 2022	01 Dec 2021
hrs	Client Info		1324	1214	1178
			NORMAL	NORMAL	NORMAL
ΙΤ	method	limit/base	current	history1	history2
ppm	ASTM D5185m		0	0	6
	method	limit/base	current	history1	history2
ppm	ASTM D5185m	<1.0	0	0	0
ppm	ASTM D5185m	<0.1	<1	0	0
ppm	ASTM D5185m	<0.1	0	0	0
	method	limit/base	current	history1	history2
ppm	ASTM D5185m	<0.1	0	0	0
ppm	ASTM D5185m	<0.1	0	0	0
ppm	ASTM D5185m	<0.1	0	0	0
ppm	ASTM D5185m	<0.1	0	0	0
ppm	ASTM D5185m	< 0.1	0	0	0
ppm	ASTM D5185m	<0.1	0	0	0
ppm	ASTM D5185m	<0.1	0	0	0
ppm	ASTM D5185m	<0.1	<1	0	0
ppm	ASTM D5185m	<0.1	0	0	0
	method	limit/base	current	history1	history2
				3416	
	ppm	Client Info Client Info Client Info Client Info Client Info The method Popm ASTM D5185m Popm ASTM D5185m	Client Info Client Info	Client Info 29 Sep 2023	Client Info Client Info



FUEL REPORT







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10740394

: WC0834507 : 06006632 Test Package : MOB 1

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 13 Nov 2023 Diagnosed : 16 Nov 2023 Diagnostician : Jonathan Hester

To discuss this sample report, contact Customer Service at 1-800-237-1369.

NEW WINDSOR, NY US 12553 Contact: JOE SAYEGH joe@gentechltd.com T: (845)568-0500 F: (845)568-3073

GEN TECH LTD

3017 RT 9W