

PROBLEM SUMMARY


IR ULTRA COOLANT [056638] Machine Id INGERSOLL RAND NL1077U13202 - P&H MFG

Component

Compressor



COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you follow the water drain-off procedure for this component. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status				ATTENTION					
Water	%	ASTM D6304	>0.1	△ 0.420					
ppm Water	ppm	ASTM D6304	>1000	4200					
Emulsified Water	scalar	*Visual	>0.1	0.2%					

Customer Id: UCJOHSAI Sample No.: UCH06007051 Lab Number: 06007051 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Water Drain-off			?	We advise that you follow the water drain-off procedure for this component.		
Resample			?	We recommend an early resample to monitor this condition.		

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

IR ULTRA COOLANT [056638] Machine Id INGERSOLL RAND NL1077U13202 - P&H MFG

Component

Compressor



DIAGNOSIS

Recommendation

We advise that you follow the water drain-off procedure for this component. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a moderate concentration of water present in the oil.

Fluid Condition

The AN level is acceptable for this fluid.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UCH06007051		
Sample Date		Client Info		25 Oct 2023		
Machine Age	hrs	Client Info		28753		
Oil Age	hrs	Client Info		7242		
Oil Changed		Client Info		Not Changd		
Sample Status				ATTENTION		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	<1		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m		<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	1		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>50	<1		
Tin	ppm	ASTM D5185m	>15	0		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0		
Barium	ppm	ASTM D5185m	500	609		
Molybdenum	ppm	ASTM D5185m	0	0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	0	1		
Calcium	ppm	ASTM D5185m	0	4		
Phosphorus	ppm	ASTM D5185m	20	21		
Zinc	ppm	ASTM D5185m	0	2		
Sulfur	ppm	ASTM D5185m	200	238		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	2		
Sodium	ppm	ASTM D5185m		53		
Potassium	ppm	ASTM D5185m	>20	6		
Water	%	ASTM D6304	>0.1	△ 0.420		
ppm Water	ppm	ASTM D6304	>1000	4200		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2

Acid Number (AN)

mg KOH/g ASTM D8045

0.41



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number Unique Number

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : UCH06007051

: 06007051 : 10740813

Received : 14 Nov 2023 Diagnosed : 23 Nov 2023 Diagnostician : Don Baldridge

Test Package : IND 2 (Additional Tests: KF)

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

JOHN HENRY FOSTER COMPANY

4700 LEBOURGET STREET SAINT LOUIS, MO

US 63134

Contact: RACHEL VON HATTEN

rvonhatten@jhf.com

T: (314)593-1267

F: (314)874-0965