


PROBLEM SUMMARY


ÜLTRA FG [OIL-42446] INGERSOLL RAND NK1460U13019 - SINCLAIR & RUSH

Compressor

Component



COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL			
Tin	ppm	ASTM D5185m	>15	^ 29			

Customer Id: UCJOHSAI **Sample No.:** UCH06007063 Lab Number: 06007063 Test Package: IND 2 To manage this report scan the QR code To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Resample			?	We recommend an early resample to monitor this condition.		

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

OIL ANALTOIS HEI OITI

ULTRA FG [OIL-42446] Machine Id INGERSOLL RAND NK1460U13019 - SINCLAIR & RUSH

Component

Compressor



DIAGNOSIS

Recommendation

No corrective action is recommended at this time. We recommend an early resample to monitor this condition.

Wear

The tin level is abnormal. All other component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Nov2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UCH06007063		
Sample Date		Client Info		02 Nov 2023		
Machine Age	hrs	Client Info		27002		
Oil Age	hrs	Client Info		4849		
Oil Changed		Client Info		Not Changd		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m		0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	1		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>50	<1		
Tin	ppm	ASTM D5185m	>15	<u>^</u> 29		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
	PP111					
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		74		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		3		
Calcium	ppm	ASTM D5185m		17		
Phosphorus	ppm	ASTM D5185m		248		
Zinc	ppm	ASTM D5185m		5		
Sulfur	ppm	ASTM D5185m		571		
CONTAMINANTS	6	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	3		
Sodium	ppm	ASTM D5185m		19		
Potassium	ppm	ASTM D5185m	>20	2		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.24		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual		NEG		
	oodidi	rioddi				



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number

: 06007063 Unique Number : 10740825 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : UCH06007063 Received : 14 Nov 2023 Diagnosed : 15 Nov 2023

Diagnostician : Doug Bogart

US 63134 Contact: RACHEL VON HATTEN

4700 LEBOURGET STREET

JOHN HENRY FOSTER COMPANY

rvonhatten@jhf.com

SAINT LOUIS, MO

T: (314)593-1267 F: (314)874-0965

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)