

PROBLEM SUMMARY

Sample Rating Trend




RK 122807

Component

Middle Hydraulic System

NOT GIVEN (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where dirt can enter the system. We recommend you service the filters on this component if applicable. We recommend an early resample to monitor this condition.

PROBLEMATIC	TEST RE	SULTS			
Sample Status				SEVERE	
Silicon	ppm	ASTM D5185m	>20	216	

Customer Id: SIDGRATX
Sample No.: WC0850959
Lab Number: 06007318
Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:
Don Baldridge +1
don.b505@comcast.net


To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description	
Change Filter			?	We recommend you service the filters on this component if applicable.	
Resample			?	We recommend an early resample to monitor this condition.	
Check Dirt Access			?	We advise that you check all areas where dirt can enter the system.	

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT





RK 122807

Middle Hydraulic System

NOT GIVEN (--- GAL)

D	IΑ	GI	N	O	S	IS

Recommendation

We advise that you check all areas where dirt can enter the system. We recommend you service the filters on this component if applicable. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

Elemental level of silicon (Si) above normal.


Fluid Condition

The condition of the oil is acceptable for the time in service.

				Oct2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0850959		
Sample Date		Client Info		31 Oct 2023		
Machine Age	hrs	Client Info		226		
Oil Age	hrs	Client Info		11453		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	0		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		<1		
Aluminum	ppm	ASTM D5185m	>10	2		
Lead	ppm	ASTM D5185m	>10	<1		
Copper	ppm		>75	5		
Coppei Tin	ppm	ASTM D5185m	>10	0		
Vanadium		ASTM D5185m	>10	0		
	ppm			0		
Cadmium	ppm	ASTM D5185m				
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		6		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		<1		
Calcium	ppm	ASTM D5185m		69		
Phosphorus	ppm	ASTM D5185m		375		
Zinc	ppm	ASTM D5185m		417		
Sulfur	ppm	ASTM D5185m		1056		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	216		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	<1		
Water	%	ASTM D6304	>0.1	0.053		
opm Water	ppm	ASTM D6304	>1000	530		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	0.2%		
Free Water	scalar	*Visual	,	NEG		
TOO VVAIO	Jodiai	Visual		IILG		



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number Unique Number : 10741080

: WC0850959 : 06007318

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Nov 2023 Diagnosed : 16 Nov 2023

Diagnostician : Don Baldridge

Test Package : FLEET (Additional Tests: KF) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

SIDDONS MARTIN EMERGENCY GROUP

1821 S STATE HWY 161 GRAND PRAIRIE, TX US 75051

Contact: L MONSCHKE

Imonschke@siddons-martin.com

Submitted By: RANDY PRICE

T: F:

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)